Porm 3160-5 (April2004)

# OCD-ARTESIA

### UNITEDSTATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

## SUNDRY NOTICES AND REPORTS ON WELLS

SUNDRY NOTICES AND REPORTS ON WELLS					rial No 10 10 10 10 10 10 10 10 10 10 10 10 10	
Do not use this form for proposals to drill or to re-enter an abandoned well. Use Form 3160-3 (APD) for such proposals.					Allottee or Tribe Name	
SUBMIT IN TRIPLICATE - Other instructions on reverse side.					7 If Unit or CA/Agreement, Name and/or No-NMNM68294X	
1 Type of Well Oil Well	Gas Well Other			8 Well Nai		
2 Name of Operator					y Unit #163	
BOPCO, L P.					9 API Well No	
Ba Address					30-015-35348  10 Field and Pool, or Exploratory Area	
4 Location of Well (Footage, Sec, T, R, M, or Survey Description)					Golden Lane (Morrow)	
1650' FNL, 660' FWL, Sec 9, T21S, R29E					11 County or Parish, State Eddy NM	
12 CHECK AF	PPROPRIATE BOX(ES)T	O INDICATE NATUR	E OF NOTICE, R	EPORT, OF	R OTHER DATA	
TYPE OF SUBMISSION	TYPE OF ACTION					
Notice of Intent  Subsequent Report  Final Abandonment Notice	Acidize AlterCasing Casing Repair Change Plans Convert to Injection	Deepen FractureTreat New Construction Plug and Abandon X Plug Back	Production (Start/Resume) Reclamation Recomplete Temporarily Abandon Water Disposal		Water Shut-Off Well Integrity  Other Plug back Lower Morrow & perf Middle Morrow	

13 Describe Proposed or Completed Operation (clearly state all pertinent details, including estimated starting date of any proposed work and approximate duration thereof If the proposal is to deepen directionally or recomplete horizontally, give subsurface locations and measured and true vertical depths of all pertinent markers and zones Attach the Bond under which the work will be performed or provide the Bond No on file with BLM/BIA Required subsequent reports shall be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion or recompletion in a new interval, a Form 3160-4 shall be filed once testing has been completed. Final Abandonment Notices shall be filed only after all requirements, including reclamation, have been completed, and the operator has determined that the site is ready for final inspection )

BOPCO, L.P respectfully requests permission to permanently abandon the Lower Morrow perfs @ 12,768'-12,840' by dropping an Owen 10K glass disk 2-3/8" CIBP, w/ Class "H" cmt, in the tailpipe of tbg. A 5-1/2" Baker Model "D" pkr will be set @ 12,740' & capped w/ 25 sxs cmt. Middle Morrow perfs will be added 12,672'-12,390' w/ a Baker Model "D" pkr w/ glass disk & WEG set @ 12,365'. Duncan Whitlock, of the BLM, has approved this procedure in lieu of running a MIT (originally required by the BLM as a condition of TA approval March 24, 2010).

# SEE ATTACHED FOR CONDITIONS OF APPROVAL

FORMAPP:

OM B No

Expires


5 Lease Serial No.

			98%	
14 I hereby certify that the foregoing is true and correct Name (Printed/Typed)				
Valerie Truax	Title	Title Regulatory Admin Assistant		
Signature Pollin Snead	Date	04/23/2010	APPROVED	
THIS SPACE FOR FE	DERAL OR	STATE OFFICE US	E	
Approved by		Title	Date MAY 2 8 2010	
Conditions of approval, if any, are attached Approval of this notice do certify that the applicant holds legal or equitable title to those rights in which would entitle the applicant to conduct operations thereon	Office	/s/ Chris Walls BUREAU OF LAND MANAGEMENT CARLSBAD FIELD OFFICE		
Title 18 U.S.C. Section 1001 and Title 43 U.S.C. Section 1212, make it a States any false, fictious or fraudulent statements or representation.				

(Instructions on page 2)

m

### PROPOSED WELLBORE DIAGRAM



Big Eddy Unit 163 30-015-35348 BOPCO, L.P. May 26, 2010 Conditions of Approval

- 1. Contact BLM 575-361-2822 a minimum of 4 hours prior to setting CIBP above Morrow perfs.
- 2. A minimum of 25 sxs of cement must be pumped on top of CIBP at 12,740'. WOC and tag at 12,510' or shallower.
- 3. Surface disturbance beyond the existing pad must have prior approval.
- 4. Closed loop system required.
- 5. A minimum of a 5M BOP is required and must be tested prior to performing operations. All blowout preventer (BOP) and related equipment (BOPE) shall comply with well control requirements as described in Onshore Oil and Gas Order No. 2 and API RP 53 Sec. 17.
- 6. Subsequent sundry with well test required.
- 7. Work to be completed within 90 days.

CRW 052610