Form 3160-5 (April 2004)

JUN 21 2010

	BUREAU OF LAND MAN		NMOCD /	RTESIA Afters March 31, 2007	
SUNDRY NOTICES AND REPORTS ON WELLS			NM-0560353		
Do not use this form for proposals to drill or to re-enter an abandoned well. Use Form 3160-3 (APD) for such proposals.				6 If Indian, Allottee or Tribe Name	
SUBMIT IN TRIPLICATE- Other instructions on reverse side.			7 If Unit or CA/Agreement, Name and/or No		
1 Type of Well Gas Well Other Gas Well Other				8 Well Name and No. MUNCHKIN FEDERAL #19 9 API Well No	
2 Name of Operator CHI OPERATING, INC.					
3a Address P. O. BOX 1799, MIDLAND, TX 79702		3b Phone No (include area code) 432-685-5001		30-015-37986 10 Field and Pool, or Exploratory Area	
4 Location of Well (Footage, Sec., T., R., M., or Survey Description)				Benson Delaware	
2310' FNL & 320' FEL, Sec. 11-T19S-R30E SHL				11 County or Parish, State	
1300' FNL & 1000' FEL Sec. 1		EDDY,NM			
12 CHECK AI	PPROPRIATE BOX(ES) TO	INDICATE NATURI	E OF NOTICE, R	EPORT, OR OTHER DATA	
TYPE OF SUBMISSION	TYPE OF ACTION				
If the proposal is to deepen dire Attach the Bond under which it following completion of the in- testing has been completed. Fit determined that the site is ready 1. Run Freepoint back off 2. TOH w/Fishing tools or 3. TIH w/Drl Pipe, open et 4. Set cmt balance plug fo and vac. trk to haul off. 5. TOH LD excess Drill Pi on way from Weatherfe lost circ 4191-4206'. We	ectionally or recomplete horizontally he work will be performed or provivolved operations. If the operation hal Abandonment Notices shall be of for final inspection. The fish stand Drill Collars in Drinded to Top of fish, circ, mover kick off, as per BJ spees. To Note: Give BJ hr. notice. hee and all off Drill Collars, Plord) THH tag cmt plug and drivatherford Dir Driller will let use F spees so we can drill to TD weet work with the speed of the provided to TD weet and drill to TD weet	ly, give subsurface location ide the Bond No on file we results in a multiple complified only after all requirent ke LD/tools. e pipe. He t/4000' (+-), Circ excurrent He t/4000' (+-), Circ	as and measured and truth BLM/BIA Requiretion or recompletion nents, including reclan ess cmt out of hole tooth bit that is on lever Weatherford	Well Integrity ✓ Other KICK OFF POINT bandon	
Sidetrack plan and view is attached.			Operator must have an API number prior to any sales.		
14 I hereby certify that the fore	egoing is true and correct				
Name (Printed/Typed) ROBINIASKEW		Title R	Title REGULATORY CLERK		
Signature XX (TW) (b) (l)		Date	1	06/01/2 0 10 ADDOVED	

certify that the applicant holds legal or equitable title to those rights in the subject lease Office BURFAU OF LAND MANAGEMENT which would entitle the applicant to conduct operations thereon Title 18 USC Section 1001 and Title 43 USC Section 1212, make it a crime for any person knowingly and willfully to make to any department/eDageto/Dougle Jointed States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction

Title

THIS SPACE FOR FEDERAL OR STATE OFFICE US



Conditions of approval, if any, are attached Approval of this notice does not warrant or

Approved by