

Submit 1 Copy To Appropriate District Office	State of New Mexico Energy, Minerals and Natural Resources			Form C-103 October 13, 2009			
<u>District I</u> 1625 N. French Dr., Hobbs, NM 88240	Energy, Minerals at	WELL API NO.					
District II 1301 W. Grand Ave., Artesia, NM 88210	OIL CONSERVA	30-015-01524					
District III	1220 South St. Francis Dr.			5. Indicate Type of Lease STATE FEE			
1000 Rio Brazos Rd., Aztec, NM 87410 District IV	Santa Fe, NM 87505			6. State Oil & Gas Lease No.			
1220 S. St. Francis Dr , Santa Fe, NM 87505					B6251		
SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A 7. Lease Name or Unit Agreement Name							
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-13) FOR SUCH \ -				Wentz State			
PROPOSALS.) 1. Type of Well: Oil Well	Cos Well Cothon			8. Well Number 2			
2. Name of Operator	JUN 2 5 2010			9. OGRID Nu	mber		
3. Address of Operator	Doral Energy Corp. NMOCD			10 Pool name	261198		
415 W. Wall St	X 79701		10. Pool name or Wildcat AID; Yates-Seven Rivers				
4. Well Location							
Unit Letter P:	330 feet from the	South	line and	990 feet		<u>East</u> line	
Section 24	Township	17S Ran		NMPM	Eddy (County	
11. Elevation (Show whether DR, RKB, RT, GR, etc.) 3,671' GR							
是是一种,我们就是一个一个一个一个一个一个一个一个一个一个一个一个一个一个一个一个一个一个一个							
12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data							
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:							
PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK ALTERING CASING							
TEMPORARILY ABANDON ☑ CHANGE PLANS ☐ COMMENCE DRILLING OPNS.☐ P AND A ☐							
PULL OR ALTER CASING / MULTIPLE COMPL CASING/CEMENT JOB							
DOWNHOLE COMMINGLE: The state of the state o							
OTHER:		□ ОТЬ	IER:				
13. Describe proposed or completed operations. (Clearly, state all pertinent details, and give pertinent dates, including estimated date							
of starting any proposed work): SEE RULE 19:15:7.14 NMAC: For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.							
proposed completion of recompletion.							
Remove production equipment and TA as follows: 1. Pull out of hole and lay down production equipment							
2. Set CIBP @ 800'		1		QIT.	1		
1. Pull out of hole and lay down production equipment 2. Set CIBP @ 800' 3. Load & test casing							
4. TA well							
	Ÿ.						
·		Г					
Spud Date: 04/12/19	Rig Re	ease Date:	0	6/10/1953			
<u> </u>		L					
I hereby certify that the information above is true and complete to the best of my knowledge and belief.							
SIGNATURE TITLE Vice President of Operations DATE 06/22/2010							
Type or print name C. M. Bloody	vorth, P.E. E-mail add	ress: marty	b@doralene	rgy.com PHON	JE: 432/780)-1180	
For State Use Only	D man acc		~ lecan aiciici	Literalia IIIOI	12. <u>134/107</u>	1100	
ADDDOVED DV.	ידוריו די			-	NA TE		
APPROVED BY: Conditions of Approval (if any):	TITLE			L	DATE		



Current Oplablao10

M



Proposed TA
Oblaal 2010

MA