Submit 1 Copy To Appropriate District State of I	New Mexico	Form C-103
Office District I Energy, Minerals	and Natural Resources	October 13, 2009
1625 N. French, Dr., Hobbs, NM 88240		WELL API NO.
District III 1301 W. Grand Ave., Artesia, NM 88210 OIL CONSERV	ATION DIVISION	30-015-32570
District III 1220 South	St. Francis Dr.	5. Indicate Type of Lease STATE FEE
1000 Rio Brazos Rd., Aztec, NM 87410 District IV Santa Fe	, NM 87505	6. State Oil & Gas Lease No.
1220 S. St. Francis Dr., Santa Fe, NM	,	VO-6377
87505 SUNDRY NOTICES AND REPORTS ON	IWEIIC	7. Lease Name or Unit Agreement Name
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEP		7. Lease Name of Olm Agreement Name
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM	A CHANTON SUCH	EL PRESIDENTE STATE
PROPOSALS.) 1. Type of Well: Oil Well ☐ Gas Well ☒ Other	RECEIVED	8. Well Number 2
2. Name of Operator	SEP 2 7 2010	9. OGRID Number
NADEL AND GUSSMAN PERMIAN LLC	OE1 2 1 2010	155615
3. Address of Operator	NMOCD ARTESI	10. Pool name or Wildcat
601 N MARIENFELD		BLACK RIVER MORROW
4. Well Location		
	SOUTH line and	
Section 2 Township 2		NMPM EDDY County
11. Elevation (Show wh	ether DR, RKB, RT, GR, et	c.)
12. Check Appropriate Box to Inc	dicate Natura of Notice	Poport or Other Data
12. Check Appropriate Box to the	uicale mature of motion	e, Report of Other Data
NOTICE OF INTENTION TO:	SU	BSEQUENT REPORT OF:
PERFORM REMEDIAL WORK PLUG AND ABANDON	☐ REMEDIAL WO	RK ⊠ ALTERING CASING □
TEMPORARILY ABANDON	☐ COMMENCE D	RILLING OPNS. P AND A
PULL OR ALTER CASING MULTIPLE COMPL	☐ CASING/CEME	NT JOB
DOWNHOLE COMMINGLE	i	
DOWNHOLE COMMININGLE		
_	OTHER:	WORKOVER
OTHER:		WORKOVER Indigive pertinent dates, including estimated date
_	state all pertinent details, a	and give pertinent dates, including estimated date
OTHER: 13. Describe proposed or completed operations. (Clearly	state all pertinent details, a	and give pertinent dates, including estimated date
OTHER: 13. Describe proposed or completed operations. (Clearly of starting any proposed work). SEE RULE 19.15.7.	state all pertinent details, a	and give pertinent dates, including estimated date
OTHER: 13. Describe proposed or completed operations. (Clearly of starting any proposed work). SEE RULE 19.15.7. proposed completion or recompletion.	state all pertinent details, a 14 NMAC. For Multiple C	and give pertinent dates, including estimated date
OTHER: 13. Describe proposed or completed operations. (Clearly of starting any proposed work). SEE RULE 19.15.7. proposed completion or recompletion. 08/26/10 MIRU CT UNIT PULL OUT CT VELOCITY STRI	state all pertinent details, a 14 NMAC. For Multiple C	and give pertinent dates, including estimated date
OTHER: 13. Describe proposed or completed operations. (Clearly of starting any proposed work). SEE RULE 19.15.7. proposed completion or recompletion. 08/26/10 MIRU CT UNIT PULL OUT CT VELOCITY STRI 08/27/10 MIRU PU. UNLOAD AND RACK 2-7/8" PROD ST	state all pertinent details, a 14 NMAC. For Multiple C	and give pertinent dates, including estimated date
OTHER: 13. Describe proposed or completed operations. (Clearly of starting any proposed work). SEE RULE 19.15.7. proposed completion or recompletion. 08/26/10 MIRU CT UNIT PULL OUT CT VELOCITY STRI 08/27/10 MIRU PU. UNLOAD AND RACK 2-7/8" PROD ST 08/28/10 – SET CIBP AND CAP W\ 10' CMT	state all pertinent details, a 14 NMAC. For Multiple C ING TRING	and give pertinent dates, including estimated date ompletions: Attach wellbore diagram of
OTHER: 13. Describe proposed or completed operations. (Clearly of starting any proposed work). SEE RULE 19.15.7. proposed completion or recompletion. 08/26/10 MIRU CT UNIT PULL OUT CT VELOCITY STRI 08/27/10 MIRU PU. UNLOAD AND RACK 2-7/8" PROD ST 08/28/10 – SET CIBP AND CAP W\ 10' CMT 09/01/10 RUN TCP GUN ASSEMBLY SET PKR @ 12,212 S 09/02/10 PERFORATE THE MORROW NO FLOW.	state all pertinent details, a 14 NMAC. For Multiple C ING IRING SPOT GUNS TO PERFOR	and give pertinent dates, including estimated date ompletions: Attach wellbore diagram of
OTHER: 13. Describe proposed or completed operations. (Clearly of starting any proposed work). SEE RULE 19.15.7. proposed completion or recompletion. 08/26/10 MIRU CT UNIT PULL OUT CT VELOCITY STRI 08/27/10 MIRU PU. UNLOAD AND RACK 2-7/8" PROD ST 08/28/10 – SET CIBP AND CAP W\ 10' CMT 09/01/10 RUN TCP GUN ASSEMBLY SET PKR @ 12,212 S 09/02/10 PERFORATE THE MORROW NO FLOW. 09/07/10 ACIDIZE THE MORROW WITH 2500 GALS OF 7	state all pertinent details, a 14 NMAC. For Multiple C ING IRING SPOT GUNS TO PERFOR 7-1/2% HC1	and give pertinent dates, including estimated date ompletions: Attach wellbore diagram of ATE THE MORROW @ 12,280-12,292
OTHER: 13. Describe proposed or completed operations. (Clearly of starting any proposed work). SEE RULE 19.15.7. proposed completion or recompletion. 08/26/10 MIRU CT UNIT PULL OUT CT VELOCITY STRI 08/27/10 MIRU PU. UNLOAD AND RACK 2-7/8" PROD ST 08/28/10 – SET CIBP AND CAP W\ 10' CMT 09/01/10 RUN TCP GUN ASSEMBLY SET PKR @ 12,212 S 09/02/10 PERFORATE THE MORROW NO FLOW.	state all pertinent details, a 14 NMAC. For Multiple C ING IRING SPOT GUNS TO PERFOR 7-1/2% HC1	and give pertinent dates, including estimated date ompletions: Attach wellbore diagram of ATE THE MORROW @ 12,280-12,292
OTHER: 13. Describe proposed or completed operations. (Clearly of starting any proposed work). SEE RULE 19.15.7. proposed completion or recompletion. 08/26/10 MIRU CT UNIT PULL OUT CT VELOCITY STRI 08/27/10 MIRU PU. UNLOAD AND RACK 2-7/8" PROD ST 08/28/10 – SET CIBP AND CAP W\ 10' CMT 09/01/10 RUN TCP GUN ASSEMBLY SET PKR @ 12,212 S 09/02/10 PERFORATE THE MORROW NO FLOW. 09/07/10 ACIDIZE THE MORROW WITH 2500 GALS OF 7	state all pertinent details, a 14 NMAC. For Multiple C ING IRING SPOT GUNS TO PERFOR 7-1/2% HC1	and give pertinent dates, including estimated date ompletions: Attach wellbore diagram of ATE THE MORROW @ 12,280-12,292
OTHER: 13. Describe proposed or completed operations. (Clearly of starting any proposed work). SEE RULE 19.15.7. proposed completion or recompletion. 08/26/10 MIRU CT UNIT PULL OUT CT VELOCITY STRI 08/27/10 MIRU PU. UNLOAD AND RACK 2-7/8" PROD ST 08/28/10 – SET CIBP AND CAP W\ 10' CMT 09/01/10 RUN TCP GUN ASSEMBLY SET PKR @ 12,212 S 09/02/10 PERFORATE THE MORROW NO FLOW. 09/07/10 ACIDIZE THE MORROW WITH 2500 GALS OF 7	state all pertinent details, a 14 NMAC. For Multiple C ING IRING SPOT GUNS TO PERFOR 7-1/2% HC1	and give pertinent dates, including estimated date ompletions: Attach wellbore diagram of ATE THE MORROW @ 12,280-12,292
OTHER: 13. Describe proposed or completed operations. (Clearly of starting any proposed work). SEE RULE 19.15.7. proposed completion or recompletion. 08/26/10 MIRU CT UNIT PULL OUT CT VELOCITY STRI 08/27/10 MIRU PU. UNLOAD AND RACK 2-7/8" PROD ST 08/28/10 – SET CIBP AND CAP W\ 10' CMT 09/01/10 RUN TCP GUN ASSEMBLY SET PKR @ 12,212 S 09/02/10 PERFORATE THE MORROW NO FLOW. 09/07/10 ACIDIZE THE MORROW WITH 2500 GALS OF 7 09/12/10 SELLING GAS ON A 9/16 CHOKE @ 3400 PSI , 1	state all pertinent details, at 14 NMAC. For Multiple Confidence of the NMAC. For Mul	and give pertinent dates, including estimated date ompletions: Attach wellbore diagram of ATE THE MORROW @ 12,280-12,292
OTHER: 13. Describe proposed or completed operations. (Clearly of starting any proposed work). SEE RULE 19.15.7. proposed completion or recompletion. 08/26/10 MIRU CT UNIT PULL OUT CT VELOCITY STRI 08/27/10 MIRU PU. UNLOAD AND RACK 2-7/8" PROD ST 08/28/10 – SET CIBP AND CAP W\ 10' CMT 09/01/10 RUN TCP GUN ASSEMBLY SET PKR @ 12,212 S 09/02/10 PERFORATE THE MORROW NO FLOW. 09/07/10 ACIDIZE THE MORROW WITH 2500 GALS OF 7 09/12/10 SELLING GAS ON A 9/16 CHOKE @ 3400 PSI , 1	state all pertinent details, a 14 NMAC. For Multiple C ING IRING SPOT GUNS TO PERFOR 7-1/2% HC1	and give pertinent dates, including estimated date ompletions: Attach wellbore diagram of ATE THE MORROW @ 12,280-12,292
OTHER: 13. Describe proposed or completed operations. (Clearly of starting any proposed work). SEE RULE 19.15.7. proposed completion or recompletion. 08/26/10 MIRU CT UNIT PULL OUT CT VELOCITY STRI 08/27/10 MIRU PU. UNLOAD AND RACK 2-7/8" PROD ST 08/28/10 – SET CIBP AND CAP W\ 10' CMT 09/01/10 RUN TCP GUN ASSEMBLY SET PKR @ 12,212 S 09/02/10 PERFORATE THE MORROW NO FLOW. 09/07/10 ACIDIZE THE MORROW WITH 2500 GALS OF 7 09/12/10 SELLING GAS ON A 9/16 CHOKE @ 3400 PSI , 1	state all pertinent details, at 14 NMAC. For Multiple Confidence of the NMAC. For Mul	and give pertinent dates, including estimated date ompletions: Attach wellbore diagram of ATE THE MORROW @ 12,280-12,292
OTHER: 13. Describe proposed or completed operations. (Clearly of starting any proposed work). SEE RULE 19.15.7. proposed completion or recompletion. 08/26/10 MIRU CT UNIT PULL OUT CT VELOCITY STRI 08/27/10 MIRU PU. UNLOAD AND RACK 2-7/8" PROD ST 08/28/10 – SET CIBP AND CAP W\ 10' CMT 09/01/10 RUN TCP GUN ASSEMBLY SET PKR @ 12,212 S 09/02/10 PERFORATE THE MORROW NO FLOW. 09/07/10 ACIDIZE THE MORROW WITH 2500 GALS OF 7 09/12/10 SELLING GAS ON A 9/16 CHOKE @ 3400 PSI , 1	state all pertinent details, at 14 NMAC. For Multiple Confidence of the NMAC. For Mul	and give pertinent dates, including estimated date ompletions: Attach wellbore diagram of ATE THE MORROW @ 12,280-12,292'
OTHER: 13. Describe proposed or completed operations. (Clearly of starting any proposed work). SEE RULE 19.15.7. proposed completion or recompletion. 08/26/10 MIRU CT UNIT PULL OUT CT VELOCITY STRI 08/27/10 MIRU PU. UNLOAD AND RACK 2-7/8" PROD ST 08/28/10 – SET CIBP AND CAP W\ 10' CMT 09/01/10 RUN TCP GUN ASSEMBLY SET PKR @ 12,212 S 09/02/10 PERFORATE THE MORROW NO FLOW. 09/07/10 ACIDIZE THE MORROW WITH 2500 GALS OF 7 09/12/10 SELLING GAS ON A 9/16 CHOKE @ 3400 PSI , 1	state all pertinent details, at 14 NMAC. For Multiple Confidence of the NMAC. For Mul	and give pertinent dates, including estimated date ompletions: Attach wellbore diagram of ATE THE MORROW @ 12,280-12,292'
OTHER: 13. Describe proposed or completed operations. (Clearly of starting any proposed work). SEE RULE 19.15.7. proposed completion or recompletion. 08/26/10 MIRU CT UNIT PULL OUT CT VELOCITY STRI 08/27/10 MIRU PU. UNLOAD AND RACK 2-7/8" PROD ST 08/28/10 – SET CIBP AND CAP W\ 10' CMT 09/01/10 RUN TCP GUN ASSEMBLY SET PKR @ 12,212 S 09/02/10 PERFORATE THE MORROW NO FLOW. 09/07/10 ACIDIZE THE MORROW WITH 2500 GALS OF 7 09/12/10 SELLING GAS ON A 9/16 CHOKE @ 3400 PSI , 1 Spud Date: Rig R	state all pertinent details, at 14 NMAC. For Multiple Confidence of the NMAC. For Mul	and give pertinent dates, including estimated date ompletions: Attach wellbore diagram of ATE THE MORROW @ 12,280-12,292' WPD
OTHER: 13. Describe proposed or completed operations. (Clearly of starting any proposed work). SEE RULE 19.15.7. proposed completion or recompletion. 08/26/10 MIRU CT UNIT PULL OUT CT VELOCITY STRI 08/27/10 MIRU PU. UNLOAD AND RACK 2-7/8" PROD ST 08/28/10 – SET CIBP AND CAP W\ 10' CMT 09/01/10 RUN TCP GUN ASSEMBLY SET PKR @ 12,212 S 09/02/10 PERFORATE THE MORROW NO FLOW. 09/07/10 ACIDIZE THE MORROW WITH 2500 GALS OF 7 09/12/10 SELLING GAS ON A 9/16 CHOKE @ 3400 PSI , 1 Spud Date: Rig R	state all pertinent details, at 14 NMAC. For Multiple Confidence of the NMAC. For Mul	and give pertinent dates, including estimated date ompletions: Attach wellbore diagram of ATE THE MORROW @ 12,280-12,292' WPD
OTHER: 13. Describe proposed or completed operations. (Clearly of starting any proposed work). SEE RULE 19.15.7. proposed completion or recompletion. 08/26/10 MIRU CT UNIT PULL OUT CT VELOCITY STRI 08/27/10 MIRU PU. UNLOAD AND RACK 2-7/8" PROD ST 08/28/10 – SET CIBP AND CAP W\ 10' CMT 09/01/10 RUN TCP GUN ASSEMBLY SET PKR @ 12,212 String 109/02/10 PERFORATE THE MORROW NO FLOW. 09/07/10 ACIDIZE THE MORROW WITH 2500 GALS OF 70 09/12/10 SELLING GAS ON A 9/16 CHOKE @ 3400 PSI , 1 Spud Date: Rig R I hereby certify that the information above is true and complete SIGNATURE 24 M 2 M Calada TITL	State all pertinent details, at 14 NMAC. For Multiple Council of France Council of F	and give pertinent dates, including estimated date ompletions: Attach wellbore diagram of ATE THE MORROW @ 12,280-12,292 WPD Ige and belief. DATE09/22/10
OTHER: 13. Describe proposed or completed operations. (Clearly of starting any proposed work). SEE RULE 19.15.7. proposed completion or recompletion. 08/26/10 MIRU CT UNIT PULL OUT CT VELOCITY STRI 08/27/10 MIRU PU. UNLOAD AND RACK 2-7/8" PROD ST 08/28/10 – SET CIBP AND CAP W\ 10' CMT 09/01/10 RUN TCP GUN ASSEMBLY SET PKR @ 12,212 String 109/02/10 PERFORATE THE MORROW NO FLOW. 09/07/10 ACIDIZE THE MORROW WITH 2500 GALS OF 70 09/12/10 SELLING GAS ON A 9/16 CHOKE @ 3400 PSI , 1 Spud Date: Rig R Spud Date: Rig R Title Type or print name _K. MCCREADY E-ma	State all pertinent details, at 14 NMAC. For Multiple Council of France Council of F	and give pertinent dates, including estimated date ompletions: Attach wellbore diagram of ATE THE MORROW @ 12,280-12,292' WPD
OTHER: 13. Describe proposed or completed operations. (Clearly of starting any proposed work). SEE RULE 19.15.7. proposed completion or recompletion. 08/26/10 MIRU CT UNIT PULL OUT CT VELOCITY STRI 08/27/10 MIRU PU. UNLOAD AND RACK 2-7/8" PROD ST 08/28/10 – SET CIBP AND CAP W\ 10' CMT 09/01/10 RUN TCP GUN ASSEMBLY SET PKR @ 12,212 S 09/02/10 PERFORATE THE MORROW NO FLOW. 09/07/10 ACIDIZE THE MORROW WITH 2500 GALS OF 7 09/12/10 SELLING GAS ON A 9/16 CHOKE @ 3400 PSI , 1 Spud Date: Rig R I hereby certify that the information above is true and complete SIGNATURE Rig R Type or print name K. MCCREADY E-ma For State Use Only	state all pertinent details, as 14 NMAC. For Multiple Council NG FRING SPOT GUNS TO PERFOR 2-1/2% HCl 284 MCFD, 0 BOPD, 0 BV selease Date: Lete to the best of my knowled the council address: KEMM@NAG il address: KEMM@NAG	and give pertinent dates, including estimated date ompletions: Attach wellbore diagram of ATE THE MORROW @ 12,280-12,292 WPD Ige and belief. GRDATE09/22/10 USS.COM PHONE: _432-682-4429
OTHER: 13. Describe proposed or completed operations. (Clearly of starting any proposed work). SEE RULE 19.15.7. proposed completion or recompletion. 08/26/10 MIRU CT UNIT PULL OUT CT VELOCITY STRI 08/27/10 MIRU PU. UNLOAD AND RACK 2-7/8" PROD ST 08/28/10 – SET CIBP AND CAP W\ 10' CMT 09/01/10 RUN TCP GUN ASSEMBLY SET PKR @ 12,212 S 09/02/10 PERFORATE THE MORROW NO FLOW. 09/07/10 ACIDIZE THE MORROW WITH 2500 GALS OF 7 09/12/10 SELLING GAS ON A 9/16 CHOKE @ 3400 PSI , 1 Spud Date: Rig R I hereby certify that the information above is true and complete SIGNATURE Rig R Type or print name K. MCCREADY E-ma For State Use Only	State all pertinent details, at 14 NMAC. For Multiple Council of France Council of F	and give pertinent dates, including estimated date ompletions: Attach wellbore diagram of ATE THE MORROW @ 12,280-12,292 WPD Ige and belief. GRDATE09/22/10 USS.COM PHONE: _432-682-4429