

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

OCD-ARTESIA

FORM APPROVED
OMB No. 1004-0137
Expires: July 31, 2010

SUNDRY NOTICES AND REPORTS ON WELLS
Do not use this form for proposals to drill or to re-enter an abandoned well. Use Form 3160-3 (APD) for such proposals.

SUBMIT IN TRIPLICATE – Other instructions on page 2.		5. Lease Serial No. NMLCO62254A
1. Type of Well <input checked="" type="checkbox"/> Oil Well <input type="checkbox"/> Gas Well <input type="checkbox"/> Other		6. If Indian, Allottee or Tribe Name
2. Name of Operator Devon Energy Production Company, LP		7. If Unit of CA/Agreement, Name and/or No.
3a. Address PO Box 250, Artesia, NM 88211	3b. Phone No. (include area code) 575-748-3371	8. Well Name and No. Saladar 10
4. Location of Well (Footage, Sec., T., R., M., or Survey Description) 330° FSL & 1753' FEL; Unit O, Sec 33, T20S, R28E		9. API Well No. 30-015-10365
		10. Field and Pool or Exploratory Area Saladar - Yates
		11. Country or Parish, State Eddy, NM


12. CHECK THE APPROPRIATE BOX(ES) TO INDICATE NATURE OF NOTICE, REPORT OR OTHER DATA

TYPE OF SUBMISSION	TYPE OF ACTION			
<input type="checkbox"/> Notice of Intent	<input type="checkbox"/> Acidize	<input type="checkbox"/> Deepen	<input type="checkbox"/> Production (Start/Resume)	<input type="checkbox"/> Water Shut-Off
<input checked="" type="checkbox"/> Subsequent Report	<input type="checkbox"/> Alter Casing	<input type="checkbox"/> Fracture Treat	<input checked="" type="checkbox"/> Reclamation	<input type="checkbox"/> Well Integrity
<input checked="" type="checkbox"/> Final Abandonment Notice	<input type="checkbox"/> Casing Repair	<input type="checkbox"/> New Construction	<input type="checkbox"/> Recomplete	<input type="checkbox"/> Other _____
	<input type="checkbox"/> Change Plans	<input type="checkbox"/> Plug and Abandon	<input type="checkbox"/> Temporarily Abandon	
	<input type="checkbox"/> Convert to Injection	<input type="checkbox"/> Plug Back	<input type="checkbox"/> Water Disposal	

13. Describe Proposed or Completed Operation: Clearly state all pertinent details, including estimated starting date of any proposed work and approximate duration thereof. If the proposal is to deepen directionally or recomplate horizontally, give subsurface locations and measured and true vertical depths of all pertinent markers and zones. Attach the Bond under which the work will be performed or provide the Bond No. on file with BLM/BIA. Required subsequent reports must be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion or recompletion in a new interval, a Form 3160-4 must be filed once testing has been completed. Final Abandonment Notices must be filed only after all requirements, including reclamation, have been completed and the operator has determined that the site is ready for final inspection.)

Wellbore plugged and abandoned on 7/8/2010. P&A marker set. Location is ready for inspection after P&A.

Accepted for record
NMOCD



14. I hereby certify that the foregoing is true and correct. Name (Printed/Typed) Denise Menoud	Title Field Tech
Signature <i>Denise Menoud</i>	Date 7/14/2010

THIS SPACE FOR FEDERAL OR STATE OFFICE USE

Approved by	Title	Date
Conditions of approval, if any, are attached. Approval of this notice does not warrant or certify that the applicant holds legal or equitable title to those rights in the subject lease which would entitle the applicant to conduct operations thereon.	Office	

Title 18 U.S.C. Section 1001 and Title 43 U.S.C. Section 1212, make it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

SUNDRY NOTICES AND REPORTS ON WELLS

Do not use this form for proposals to drill or to re-enter an abandoned well. Use Form 3160-3 (APD) for such proposals

SUBMIT IN TRIPLICATE Other Instructions on page 2

FORM APPROVED
OMB NO. 1004-0137
EXPIRES: March 31, 2007

1 Type of Well <input checked="" type="checkbox"/> Oil Well <input type="checkbox"/> Gas Well <input type="checkbox"/> Other	
2. Name of Operator DEVON ENERGY PRODUCTION COMPANY, LP	
3a. Address 20 North Broadway, Ste 1500, Oklahoma City, OK 73102	3b. Phone No. (include area code) 405-552-4615
4. Location of Well (Footage, Sec., T., R., M. or Survey Description) 330 FSL 1753 FEL O 33 T20S R28E	

5. Lease Serial No. NMLC062254A
6. If Indian, Allottee or Tribe Name
7. Unit or CA Agreement Name and No.
8. Well Name and No. SALADAR 10
9. API Well No. 30-015-10365
10. Field and Pool, or Exploratory Area SALADAR -YATES
11. County or Parish, State EDDY NM

12. CHECK APPROPRIATE BOX(es) TO INDICATE NATURE OF NOTICE, REPORT OR OTHER DATA

TYPE OF SUBMISSION	TYPE OF ACTION			
<input type="checkbox"/> Notice of Intent	<input type="checkbox"/> Acidize	<input type="checkbox"/> Deepen	<input type="checkbox"/> Production (Start/Resume)	<input type="checkbox"/> Water Shut-Off
<input checked="" type="checkbox"/> Subsequent Report	<input type="checkbox"/> Alter Casing	<input type="checkbox"/> Fracture Treat	<input type="checkbox"/> Reclamation	<input type="checkbox"/> Well Integrity
<input type="checkbox"/> Final Abandonment Notice	<input type="checkbox"/> Casing Repair	<input type="checkbox"/> New Construction	<input type="checkbox"/> Recomplete	<input type="checkbox"/> Other
	<input type="checkbox"/> Change Plans	<input checked="" type="checkbox"/> Plug and Abandon	<input type="checkbox"/> Temporarily Abandon	
	<input type="checkbox"/> Convert to Injection	<input type="checkbox"/> Plug Back	<input type="checkbox"/> Water Disposal	

13. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work and approximate duration thereof. If the proposal deepens directionally or recompletes horizontally, give subsurface location and measured and true vertical depths of all pertinent markers and zones. Attach the Bond under which the work will be performed or provide the Bond No. on file with BLM/BIA. Required subsequent reports shall be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion or recompletion in a new interval, a Form 3160-4 shall be filed once testing has been completed. Final Abandonment Notices shall be filed only after all requirement, including reclamation, have been completed, and the operator has determined that the site is ready for final inspection)

Wellbore Plug & Abandonment Work 6/7/10 - 7/8/10

1. MIRU Clean out cellar Dug out around 5-1/2" casing. 1.5' of 5-1/2" above cellar floor
2. Install 30" conductor pipe to 26' Cement w/10 yds redi-mix. Backfill around conductor
3. Ran 7", 23# casing. Washed over 5-1/2" casing and set 7" at 43'. Cement 30" X 7" annulus w/10 yds redi-mix.
4. Washed, milled, and retrieved 2-3/8" tubing & rod string down to 532' TOF at 532'.
5. Milled over fish. Made 1' in 2 hrs. Obtained verbal approval from Duncal Whitlock to P&A from 532'
6. TIH w/2-3/8" tubing to 532' Pump 13 bbl, 14.8 ppg Cl C cement from 532' to surface. RDMO
7. Cut casings off 3' BGL. Set P&A marker.
8. Wellbore plugged & abandoned on 7/8/2010

14. I hereby certify that the foregoing is true and correct Name: Ronnie Slack	Title Operations Technician
Signature <i>Ronnie Slack</i>	Date 7/8/2010

THIS SPACE FOR FEDERAL OR STATE OFFICE USE

Approved by	Title	Date
Conditions of approval, if any are attached. Approval of this notice does not warrant or certify that the applicant holds legal or equitable title to those rights in the subject lease which would entitle the applicant to conduct or operations thereon.	Office	

DENNIS LANGLITZ OPERATOR

Well Name: SALADAR #10		Field: SALADAR YATES	
Location: 330' FSL & 1753' FEL; SEC 33-T20S-R28E		County: EDDY	State: NM
Elevation: 3195' DF		Spud Date: 6/9/64	Compl Date: 9/21/64 (producing)
API#: 30-015-10365	Prepared by: Ronnie Slack	Date: 7/8/10	Rev:

Actual P&A

Set 30" conductor @ 26'

Cemented w/10 yds redi mix (6/15/10)

Actual P&A

Washed 7", 23#, casing over 5-1/2" csg to 43'

Cemented w/10 yds redi mix (6/22/10)

Wellbore Plugged & Abandoned--7/8/10

Cut casings off 3' BGL. Set dry hole marker.

8-1/4" Hole

7", 17#, ran to 440'. Casing pulled.

(per subsequent sundry notice dated 9/6/64)

Actual P&A

Pumped 13 bbl 14.8 ppg CI C cmt from 532' to surface, circ 2 bbl cmt to pit. (6/30/10)

Actual P&A

6/23-6/29/10--Fished out 2-3/8" tubing and rod string. Remaining TOF @ 532'. Received verbal to P&A from 532' per Duncan Whitlock of BLM. (6/23-6/29/10)

6-1/4" Hole

5-1/2", 14#, @ 640'

Cmt'd w/100 sx to surface (9/6/64)

(capacity=1370 cu ft / ft)

6-1/4" open hole (capacity = 2131 cu ft / ft)

YATES FORMATION (9/21/64)

Open hole completion

730' TD