

RECEIVED

APR 20 2011

SUNDRY NOTICES AND REPORTS ON WELLS

Do not use this form for proposals to drill or to re-enter an abandoned well. Use Form 3160-3 (APD) for such proposals.

NMOCD ARTESIA

SUBMIT IN TRIPLICATE - Other instructions on reverse side

1. Type of Well

☒ Oil Well ☐ Gas Well ☐ Other

2. Name of Operator

Topat Oil Corporation

3a. Address

505 N Big Springs, Suite 405

3b. Phone No. (include area code)

(432) 682-6340

4. Location of Well (Footage, Sec., T., R., M., or Survey Description)

1980

1980

FSL, 2-18FWL Sec20 T11S R27E

5. Lease Serial No.

NMNM58803

6. If Indian, Allottee or Tribe Name

7. If Unit or CA/Agreement, Name and/or No.

8. Well Name and No.

Patricia wells 1 23

9. API Well No.

30-005-68903

10. Field and Pool, or Exploratory Area

Coyote (Queen)

11. County or Parish, State

Chaves, NM

12. CHECK APPROPRIATE BOX(ES) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

TYPE OF SUBMISSION	TYPE OF ACTION			
<input type="checkbox"/> Notice of Intent	<input type="checkbox"/> Acidize	<input type="checkbox"/> Deepen	<input type="checkbox"/> Production (Start/Resume)	<input type="checkbox"/> Water Shut-Off
<input type="checkbox"/> Subsequent Report	<input type="checkbox"/> Alter Casing	<input type="checkbox"/> Fracture Treat	<input type="checkbox"/> Reclamation	<input type="checkbox"/> Well Integrity
<input type="checkbox"/> Final Abandonment Notice	<input type="checkbox"/> Casing Repair	<input type="checkbox"/> New Construction	<input type="checkbox"/> Recomplete	<input checked="" type="checkbox"/> Other Change
	<input type="checkbox"/> Change Plans	<input type="checkbox"/> Plug and Abandon	<input type="checkbox"/> Temporarily Abandon	Operator
	<input type="checkbox"/> Convert to Injection	<input type="checkbox"/> Plug Back	<input type="checkbox"/> Water Disposal	

13. Describe Proposed or Completed Operation (clearly state all pertinent details, including estimated starting date of any proposed work and approximate duration thereof. If the proposal is to deepen directionally or recomplate horizontally, give subsurface locations and measured and true vertical depths of all pertinent markers and zones. Attach the Bond under which the work will be performed or provide the Bond No. on file with BLM/BIA. Required subsequent reports shall be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion or recomplate in a new interval, a Form 3160-4 shall be filed once testing has been completed. Final Abandonment Notices shall be filed only after all requirements, including reclamation, have been completed, and the operator has determined that the site is ready for final inspection.)

We have sold all interest in this lease and have turned over operations to Slayton Resources INC. P.O.Box 2035 Roswell, NM 80202 effective June 1, 2010.

DENIED**DENIED**14. I hereby certify that the foregoing is true and correct
Name (Printed/Typed)

Thomas E. Schneider

Title

VP Operations

Signature

Date

3-7-2011

THIS SPACE FOR FEDERAL OR STATE OFFICE USE

Approved by

DENIED /S/ DAVID R. GLASSTitle
PETROLEUM ENGINEER

Date

APR 14 2011

Slayton Resources Inc. Must Sign & Submit A Sundry Notice
(BLM Form 3160-5) With The Statement Similar To The One Shown Below.

Effective 06-01-2010, Slayton Resources Inc. Will Assume Operations Of The Well And Certifies That it Is Authorized By Proper Lease Interest Owners To Conduct Lease Operations And Is Responsible Under Terms And Conditions Of The Lease Associated With This Well. Bond Coverage Under Slayton Resources Inc.'s Statewide BLM Bond No. NMB000001.

s not warrant or
the subject lease

Office

and willfully to make to any department or agency of the United States any false, fictitious or