

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

ckf

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT" for such proposals.)

1. OIL WELL GAS WELL OTHER P&A

2. NAME OF OPERATOR
Mesa Petroleum Co.

3. ADDRESS OF OPERATOR
P. O. Box 2009 / Amarillo, Texas

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements. See also space 17 below.)
At surface
660' FSL & 1980' FWL

14. PERMIT NO.

15. ELEVATIONS (Show whether DF, RT, GR, etc.)
3968.5' GR

5. LEASE DESIGNATION AND SERIAL NO.
NM-36651

6. IF INDIAN, ALLOTTEE OR TRIBE NAME
Cindy Federal

7. UNIT AGREEMENT NAME

8. FARM OR LEASE NAME
Cindy Federal


9. WELL NO.
2

10. FIELD AND POOL, OR WILDCAT
Under - West Pecos Slope Abo

11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA
Sec. 24, T8S, R22E

12. COUNTY OR PARISH
Chaves

13. STATE
NM



16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
TEST WATER SHUT-OFF <input type="checkbox"/>	PULL OR ALTER CASING <input type="checkbox"/>	WATER SHUT-OFF <input type="checkbox"/>	REPAIRING WELL <input type="checkbox"/>
FRACTURE TREAT <input type="checkbox"/>	MULTIPLE COMPLETE <input type="checkbox"/>	FRACTURE TREATMENT <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
SHOOT OR ACIDIZE <input type="checkbox"/>	ABANDON* <input type="checkbox"/>	SHOOTING OR ACIDIZING <input type="checkbox"/>	ABANDONMENT* <input checked="" type="checkbox"/>
REPAIR WELL <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	(Other) _____	
(Other) _____		(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)	

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

Plugged well as follows on 9-23-81:

- Set 25 sx "C" from 2650' to 2550' across top of Abo.
- Set 25 sx "C" from 1534' to 1433' (50' in & out of 8 5/8" csg).
- Set 10 sx "C" from 100' to surface.
- Install Dry Hole Marker. Well P&A 9-23-81.

XC: BLM-R(0+5), WELL FILE

18. I hereby certify that the foregoing is true and correct
SIGNED R. F. [Signature] TITLE Regulatory Coordinator DATE 7-30-84

(This space for Federal or State Approval)
APPROVED BY PETER W. CHESTER TITLE _____ DATE _____
CONDITIONS OF APPROVAL, IF ANY:

