

clsr  
up

DISTRICT I  
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II  
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III  
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION  
P.O. Box 2088  
Santa Fe, New Mexico 87504-2088

WELL API NO. 30-015-01759
5. Indicate Type of Lease STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
6. State Oil & Gas Lease No. 647
7. Lease Name or Unit Agreement Name Artesia Unit
8. Well No. 16
9. Pool name or Wildcat Artesia-QN-GR-SA
10. Elevation (Show whether DF, RKB, RT, GR, etc.) GR 3674'

SUNDRY NOTICES AND REPORTS ON WELLS  
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A  
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"  
(FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well: OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>	2. Name of Operator SDX RESOURCES, INC.
3. Address of Operator P. O. BOX 5061 MIDLAND, TX 79704	4. Well Location Unit Letter E : 1980 Feet From The North Line and 660 Feet From The West Line Section 36 Township 17S Range 28E NMPM Eddy County

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data	
NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	COMMENCE DRILLING OPNS <input type="checkbox"/>
OTHER: <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
	CASING TEST AND CEMENT JOB <input type="checkbox"/>
	OTHER: <input type="checkbox"/>

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Packer and tubing was pulled. Casing tested and failed. Plan to plug and abandon well as follows:

Set CIBP @ 2136' and cap with 35 sack plug. Load hole with 10# brine. Perforate casing @ 550' and displace plug to 550'. Set 10 sx surface plug and install dry hole marker.

Well History: See attached well data sheet.

load hole w/ 25 # salt gel  
set 100' plug @ 1650'

RECEIVED

APR - 7 1995

I hereby certify that the information above is true and complete to the best of my knowledge and belief

SIGNATURE \_\_\_\_\_ TITLE VICE PRESIDENT

TYPE OR PRINT NAME JOHN POOL

OIL CON. DIV. 4/06/95  
DIST. 2

TELEPHONE NO (915) 685-1761

(This space for State Use)

ORIGINAL SIGNED BY TIM W. GUM  
DISTRICT II SUPERVISOR

APPROVED BY \_\_\_\_\_ TITLE \_\_\_\_\_

DATE MAY 15 1995

CONDITIONS OF APPROVAL, IF ANY