

CISF
JQ

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION

2040 Pacheco St.
Santa Fe, NM 87505

WELL API NO. <u>30-015-01210</u>
Indicate Type of Lease STATE <input type="checkbox"/> FEE <input type="checkbox"/>
State Oil & Gas Lease No. B-2023
Lease Name or Unit Agreement Name Old Loco Unit
Well No. 13
Pool name or Wildcat Grayburg Jackson O-G-SA

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)	
Type of Well: OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>	
Name of Operator Webb Oil Company	Well No. 13
Address of Operator 2409 Cerro Road, Artesia, NM, 88210-9757	Pool name or Wildcat Grayburg Jackson O-G-SA
Well Location Unit Letter M : 990 Feet From The South Line and 990 Feet From The West Line Section 32 Township 17S Range 29E NMPM Eddy County	
Elevation (Show whether DF, RKB, RT, GR, etc.) 3582	

11

Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☒
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐
PULL OR ALTER CASING ☐
OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐
COMMENCE DRILLING OPNS. ☐ PLUG AND ANBANDONMENT ☐
CASING TEST AND CEMENT JOB ☐
OTHER: ☐

Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Notify Ocd 24 Hrs. before starting

1. RIH spot 100' plug @ 2500 (perf. 2504 to 2670) woc & tag Min. cement Plug 25 sk.
2. Perf. 4 holes @ 765 sqz. 100' plug woc test Inside & outside 5 1/2" csg. Tag
3. Perf 5 1/2 @ 410 sqz. 200' plug (8 5/8 shoe @ 360 top salt 310) woc tag Inside & Outside 5 1/2" csg.
4. spot cmt. 30' to surface Perforate 5 1/2" csg @ 30'. Circulate cement to surface.
5. cut off well head install dry hole marker



* Brine Gel between all cement plugs.

Notific N.M.O.C.D. To witness Plugging Operations.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Wayne Brooks RDB TITLE agent

DATE 05-02-01

TYPE OR PRINT NAME Wayne Brooks

TELEPHONE NO. 915-5807161

(This space for State Use)

APPROVED BY mae (steele) TITLE Envir. Eng. Spec. I DATE 5/8/2001

CONDITIONS OF APPROVAL, IF ANY: