

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEYSUBMIT IN TRIPLICATE*
(Other instructions on reverse side)Form approved.
Budget Bureau No. 42-R1424.

5. LEASE DESIGNATION AND SERIAL NO.

LC 029426 (b)

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

7. UNIT AGREEMENT NAME

8. FARM OR LEASE NAME

H. E. West "B"

9. WELL NO.

24

10. FIELD AND POOL, OR WILDCAT

Grayburg Jackson

11. SEC., T., R., M., OR BLK. AND
SURVEY OR AREA

10-T17S-R31E

12. COUNTY OR PARISH

Eddy

13. STATE

New Mexico

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to the Federal Reserve.
Use "APPLICATION FOR PERMIT—" for such proposals.)

1. OIL WELL ☐ GAS WELL ☐ WATER INJECTION ☒	2. NAME OF OPERATOR Sinclair Oil & Gas Company OCT 1 1968
3. ADDRESS OF OPERATOR P. O. Box 1920, Hobbs, New Mexico	4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.* See also space 17 below.) At surface 660 feet from North line and 660 feet from East line of Section 10-T17S-R31E
14. PERMIT NO.	15. ELEVATIONS (Show whether DF, RT, GR, etc.) 3942'

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF ☐FRACTURE TREAT ☐SHOOT OR ACIDIZE ☐REPAIR WELL ☐(Other) ☐PULL OR ALTER CASING ☐MULTIPLE COMPLETE ☐ABANDON* ☐CHANGE PLANS ☐

SUBSEQUENT REPORT OF:

WATER SHUT-OFF ☐FRACTURE TREATMENT ☐SHOOTING OR ACIDIZING ☐(Other) Perforate, acidize & convert to WTW

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

REPAIRING WELL ☐ALTERING CASING ☐ABANDONMENT* ☐

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

3-9-66 Jet perforate Grayburg 3430-38', 3448-56', 3462-68' w/4-3/8" holes. M.A. washed Grayburg perforations 3462-68' w/500 gals. Max. Press. 2700#, Min. 1900# @ 1.4 BPM. Inst. SIP 1900#, 5 mins. SIP 1700#. MA washed Grayburg perforations 3448-56' w/500 gals. Max. Press. 2000#, Min. 1900# @ 1.5 BPM. Inst. SIP 1950#, 5 mins. SIP 1750#. M.A. washed Grayburg perfs. 3430-3468' w/1500 gals. in 3 stages, Max. Press. 2700#, Min. 1900# @ 1.2 BPM, 5 mins. SIP 1700#.

3-11-66 Ran 2-3/8" tubing and packer set @ 3309' and injected 100 bbls. fresh water into Grayburg perfs. 3396-3560' in 4 hrs. @ 100# pressure. Converted from oilwell to water injection well in Keel West Waterflood Area.

18. I hereby certify that the foregoing is true and correct

SIGNED [Signature]TITLE SuperintendentDATE 3-14-66

(This space for Federal or State office use)

APPROVED BY [Signature]
CONDITION OF APPROVAL IF ANY:

TITLE _____

DATE _____

*See Instructions on Reverse Side

Orig&2cc: USGS Artesia
cc: Regional Office
cc: fileAPPROVED
MAR 15 1966
H. L. BELL
ACTING DISTRICT ENGINEER

Instructions

General: This form is designed for submitting proposals to perform certain well operations, and reports of such operations when completed, as indicated, on Federal and Indian lands pursuant to applicable Federal law and regulations, and, if approved or accepted by any State, on all lands in such State, pursuant to applicable State law and regulations. Any necessary special instructions concerning the use of this form and the number of copies to be submitted, particularly with regard to local, area, or regional procedures and practices, either are shown below or will be issued by, or may be obtained from, the local Federal and/or State office.

Item 4: If there are no applicable State requirements, locations on Federal or Indian land should be described in accordance with Federal requirements. Consult local State or Federal office for specific instructions.

Item 17: Proposals to abandon a well and subsequent reports of abandonment should include such special information as is required by local Federal and/or State offices. In addition, such proposals and reports should include reasons for the abandonment; data on any former or present productive zones, or other zones with present significant fluid contents not sealed off by cement or otherwise; depths (top and bottom) and method of placement of cement plugs; mud or other material placed between and above plugs; amount, size, method of parting of any casing, liner or tubing pulled and the depth to top of any left in the hole; method of closing top of well; and date well site conditioned for final inspection looking to approval of the abandonment.

U.S. GOVERNMENT PRINTING OFFICE: 1963-O-685229

9 97-8 51

1968

OCT 1

EXHIBIT 10

RECEIVED
OCT 1 1968
U.S. DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT