F A C	H O U R S	QUARTER HOURS	FIELD TRIP REPORT			
I L I T Y			Name Stolenice	Date 6-47-4/	Miles District	
			Time of Departure			
			In the space below indicate the performed, listing wells or lease Signature	purpose of the trip and	the duties	
		3				
			J-12- 3' Getty ail	00 5/0 Py = 32	Replaced 104 Joints	
			Trong Ran Plastic Line with Parker Fluid Testil	1, S.T Pocker @ 323	08 Circulated 089	
			with Parker Fluid Test!	to EsoPSI		
				·		
				MY		
			Mileage	Per Diem	Hours	
				JIC	UIC	
		į		RFA	RFA	
			OtherC	Other	Other	
ASPECTION INSPECTION DRMED CLASSIFICATION					NATURE OF SPECIFIC WELL OR FACILITY INSPECTED	
usekeeping ugging ugging Cleanup 11 Test pair/Workover terflow shap or Spill ter Contamination her			related to injection project, resulting from injection into injection and production well tests, surface injection equi R = Inspections relating to Recla on O = Other = Inspections not relating	 U = Underground Injection Control - Any inspection of or related to injection project, facility, or well or resulting from injection into any well. (SWD, 2ndry injection and production wells, water flows or pressure tests, surface injection equipment, plugging, etc.) R = Inspections relating to Reclamation Fund Activity O = Other - Inspections not related to injection or The 		
			E = Indicates some form of enforce	Reclamation Fund E = Indicates some form of enforcement action taken in the field (show immediately below the letter U, R or O)		