Capy to S.T.

## NMOCC COPY

UNITED STATES SEBMIT IN TE DEPARTMENT OF THE INTERIOR STEME STATES DEPARTMENT OF THE INTERIOR STATES (Other instruction)	
SUNDRY NOTICES AND REPORTS ON WELLS  (Do not use this form for proposals to drill or to deepen or plug back to a different research use "APPLICATION FOR PERMIT—" for such proposals.)	6. IF INDIAN, ALLOTTES GE TRISE NAME
1.  OIL GAS WE'LL WELL OTHER  2. NAME OF OPERATOR	7. UNIT AGREEMENT NAME  Skelly Unit  8. FARM OR LEASE NAME
Getty Oil Company RECEIVE	9. WELL NO.
P.O. Box 730 Hobbs, New Mexico 88240 FEB 22 1078  4. LOCATION OF WELL (Report location clearly and in accordance with any State requirement).  At surface  D. C. C.	10. FIELD AND POOL, OR WILDCAT Grayburg Jackson
1980 FNL & 660 FW LARTEBIA, OFFICE	11. SEC., T., R., M., OR BLK. AND SURVEY OR ARKA
14. PERMIT NO. 15. ELEVATIONS (Show whether DF, 21, CR, e.z.)  3904 D.F.	17-31 12. COUNTY OR PARISH 13. STATE Eddy N.M.
16. Check Appropriate Box To Indicate Nature of Notice, R	
17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give per proposed work. If well is directionally drilled, give subsurface locations and measured as nent to this work.)  (1) Pull rods and tubing. (2) Run Cement Bond Log. (3) Perforate and bring cement above top of 7-Rivers. (4) Run Temperature Survey.	TMENT ALTERING CASING ABANDONMENT*  Export results of multiple completion on Well or or Recompletion Report and Log form.
18. I hereby certify that the foregoing is true and correct  SIGNED TITLE Area Superinter  (This space for Federal or State bilice use)	4070