

Form 9-331  
(May 1963)UNITED STATES  
DEPARTMENT OF THE INTERIOR  
GEOLOGICAL SURVEYSUBMIT IN TR CATE\*  
(Other instructions on re-  
verse side)Form approved.  
Budget Bureau No. 42-R1424.

5. LEASE DESIGNATION AND SERIAL NO.

LC 029395-A

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

## SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.  
Use "APPLICATION FOR PERMIT—" for such proposals.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>		7. UNIT AGREEMENT NAME	
2. NAME OF OPERATOR Sinclair Oil & Gas Company		8. FARM OR LEASE NAME Turner "A"	
3. ADDRESS OF OPERATOR P. O. Box 1920, Hobbs, New Mexico 88240		9. WELL NO. 5	
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.* See also space 17 below.) At surface 330 N 660 W		10. FIELD AND POOL, OR WILDCAT Grayburg Jackson	
14. PERMIT NO.		11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA 19-T17S-R31E NM PM	
15. ELEVATIONS (Show whether DF, RT, OR, etc.) 3733' GR		12. COUNTY OR PARISH Eddy	
		13. STATE New Mexico	

16.

## Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

## NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF ☐FRACTURE TREAT ☐SHOOT OR ACIDIZE ☐REPAIR WELL ☐

(Other) Convert oilwell to WIW

PULL OR ALTER CASING ☐MULTIPLE COMPLETE ☐ABANDON\* ☐CHANGE PLANS ☐

X

## SUBSEQUENT REPORT OF:

WATER SHUT-OFF ☐FRACTURE TREATMENT ☐SHOOTING OR ACIDIZING ☐(Other) ☐REPAIRING WELL ☐ALTERING CASING ☐ABANDONMENT\* ☐

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)\*

Present Total Depth: 3518'. PBTD 3493'. Producing from 3804-2818' & 3014-3493'  
2 BOPD and 0 BWPJ.

PROPOSE TO: Cement squeeze perfs. 2804-2818', drill out cement and test. Clean out to PBTD 3493'. Run tubing and packer set @ approx. 2939'. Convert from oilwell to water injection well in Grayburg Jackson 2939-3493', Russell-Turner Waterflood System.

RECEIVED  
NOV 2 1967  
U. S. GEOLOGICAL SURVEY  
ARTESIA, NEW MEXICO

18. I hereby certify that the foregoing is true and correct

SIGNED

TITLE Superintendent

DATE 10-27-67

(This space for Federal or State office use)

APPROVED BY

CONDITIONS OF APPROVAL, IF ANY:

TITLE

DATE

\*See Instructions on Reverse Side

Orig&2cc: USGS, Artesia  
cc: Regional Office  
cc: file