N. M. D. C. C. COPY

.NT OF THE INTERIOR verse side)

'ACATE*

Form approved. Budget Bureau No. 42-R1424. 5. LEASE DESIGNATION AND SERIAL NO.

I.C 029395 (a)

GEOLOGICAL SURVEY					
SUNDRY	NOTICES	AND	REPORTS	ON	WELLS

6.	IF	INDIAN,	ALLOTTEE	OR	TRIBE	NAME

16.	Check Appropriate Box To Indicate Nature of Notice, Report	or Other Data
14. PERM	15. ELEVATIONS (Show whether DF, RT, GR, etc.) 3658 GR	Eddy N.M.
1650' FNL & 1980' FWL (Unit letter F)		Sec. 19, T17S, R31E
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements. See also space 17 below.) At surface		Grayburg-Jackson 11. sec., T., R., M., OR BLK. AND SURVEY OR AREA
P	O. Box 1978, Roswell, New Mexico 88201	15 10. FIELD AND POOL, OR WILDCAT
A	tlantic Richfield Company	Turner "A"
OIL WELL	GAS WELL OTHER WIW	8. FARM OR LEASE NAME
(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use "APPLICATION FOR PERMIT" for such proposals.)	7. UNIT AGREEMENT NAME

Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

SUBSEQUENT REPORT OF: MOTICE OF INTENTION TO: REPAIRING WELL PULL OR ALTER CASING WATER SHUT-OFF TEST WATER SHUT-OFF ALTERING CASING FRACTURE TREATMENT MULTIPLE COMPLETE FRACTURE TREAT ABANDONMENT* SHOOTING OR ACIDIZING ABANDON* SHOOT OR ACIDIZE REPAIR WELL CHANGE PLANS (NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.) (Other)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)

A frac job in December, 1970 did not bring this well up to satisfactory water injection rates. We now propose to add perforations with two 0.42" jet shots at each depth 3320, 3321, 3322, 3326, 3327, 3328, 3333, 3334, 3338, 3339, 3340, 3352, 3353, 3354, 3358, 3359, 3360, 3368, 3369, 3372, 3374, 3377, 3382, 3383, 3385, 3386, 3387, 3389, 3390, 3396, 3397, 3398, 3400, 3401, 3403, 3405, 3406, 3407, 3414, 3416, 3418, 3420, 3422, 3424, 3425, 3426, 3427, 3428, 3431, 3432 & 3433'. Then treat all perfs $w/5000~{\rm gal}$ of 15% HCl acid and ball sealers.

18. I hereby certify that the topegoing is true and correct SIGNED O.D. D.22 tikes	Dist.	Orlg. Supervisor 1/27/71
(This space for Federal or State office use)	TITLE	HERE TO A STATE OF THE STATE OF
CONTINUE APPROVAL, IF ANY:		Section of the sectio
JOH.		Break Control

*See Instructions on Reverse Side