

(May 1963)

UNITED STATES  
DEPARTMENT OF THE INTERIOR  
GEOLOGICAL SURVEY

SUBMIT IN INK  
(Other instructions  
on reverse side)

DATE  
ON RE-

Copy to SF

Form Approved  
Budget Bureau No. 42-R1424

5. LEASE DESIGNATION AND SERIAL NO.

LC 029395 (a)

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

7. UNIT AGREEMENT NAME

8. FARM OR LEASE NAME

Turner "A"

9. WELL NO.

20

10. FIELD AND POOL, OR WILDCAT

Fren 7 Rivers

11. SEC. T., R., M., OR BLK. AND  
SURVEY OR AREA

19-T17S-R31E

12. COUNTY OR PARISH

Eddy

13. STATE

N.M.

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.  
Use "APPLICATION FOR PERMIT—" for such proposals.)

1.

OIL WELL ☒ GAS WELL ☐ OTHER ☐

2. NAME OF OPERATOR

Atlantic Richfield Company ✓

3. ADDRESS OF OPERATOR

P. O. Box 1710, Hobbs, New Mexico 88240

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.  
See also space 17 below.)  
At surface

2310' FNL & 990' FEL (Unit letter H)

14. PERMIT NO.

15. ELEVATIONS (Show whether DF, RT, GR, etc.)

3698' GR

16.

Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF

FRACTURE TREAT

SHOOT OR ACIDIZE

REPAIR WELL

(Other)

PULL OR ALTER CASING

MULTIPLE COMPLETE

ABANDON\*

CHANGE PLANS

SUBSEQUENT REPORT OF:

WATER SHUT-OFF

FRACTURE TREATMENT

SHOOTING OR ACIDIZING

(Other)

REPAIRING WELL

ALTERING CASING

ABANDONMENT\*

Plug & Abandon

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)\*

1. Rigged up on 2/25/76. POH w/rods & pump. Installed BOP. POH w/tbg & MA. RIH w/2-3/8" OD EUE tbg OE & spotted 10 bbls heavy gelled mud in OH 1866-1935'.
2. Spotted 35 sx Cl H cmt & covered bottom 180' of 5 1/2" OD casing 1686-1866' (180' cmt plug).
3. Stretched 5 1/2" csg, free point indicated @ 1029'. Cut 5 1/2" csg @ 950' & 800', csg stuck. Ran jet cutter & cut 5 1/2" csg @ 705' & recovered.
4. RIH w/2-3/8" tbg OE & spotted 45 sx Cl H cmt across 1st, 2nd & 3rd cuts 950-705'. Tagged plug @ 820'.
5. RIH w/7" cmt retr, set @ 200'. Cmt squeezed thru retr w/80 sx Cl H cmt, FP 600#. PO retr & spotted 35 sx Cl H cmt on top of retr. Spotted heavy gelled mud between all cmt plugs.
6. Spotted 10 sx Cl H cmt @ surface. Installed regulation dry hole marker. Cleaned & levelled location. P&A eff 3/2/76. Final Report.

18. I hereby certify that the foregoing is true and correct

SIGNED

TITLE Dist. Drlg. Supv.

DATE 3/5/76

(This space for Federal or State office use)

APPROVED BY

CONDITIONS OF APPROVAL, IF ANY:

TITLE

DATE

\*See Instructions on Reverse Side