

DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

(Other Instruct
verse side)

on re

Budget Bureau No. 42-R1424

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.)

5. LEASE DESIGNATION AND SERIAL NO.

LC 031844

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

7. UNIT AGREEMENT NAME

8. FARM OR LEASE NAME

Fren Oil Company

9. WELL NO.

8

10. FIELD AND POOL, OR WILDCAT

Grayburg Jackson

11. SEC., T., R., M., OR BLK. AND
SURVEY OR AREA

19-17S-31E

12. COUNTY OR PARISH

Eddy

13. STATE

N.M.

1. OIL ☒ GAS ☐ OTHER ☐ Plug & Abandon

2. NAME OF OPERATOR

Atlantic Richfield Company

3. ADDRESS OF OPERATOR

P. O. Box 1716, Hobbs, New Mexico 88240

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.
See last space if below.)
At surface

2310' FWL & 2310' FSL (Unit letter K)

14. PERMIT NO.

15. ELEVATIONS (Show whether DF, RT, GR, etc.)

3613' DF

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF ☐

FRACTURE TREAT ☐

SHOOT OR ACIDIZE ☐

REPAIR WELL ☐

(Other) ☐

PULL OR ALTER CASING ☐

MULTIPLE COMPLETE ☐

ABANDON* ☐

CHANGE PLANS ☐

SUBSEQUENT REPORT OF:

WATER SHUT-OFF ☐

FRACTURE TREATMENT ☐

SHOOTING OR ACIDIZING ☐

(Other) ☐

REPAIRING WELL ☐

ALTERING CASING ☐

ABANDONMENT* ☐

Plug & Abandon ☒

(NOTE: Report results of multiple completion on Well
Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any
proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones perti-
nent to this work.) *

Rigged up on 3/21/76, installed BOP. POH w/2716' of 2-3/8" OD EUE tbg & pkr. RIH w/4 1/2" CIBP & set @ 2710'. Spotted 4 sx Cl H cmt (35') on top of CIBP. Checked top of cmt plug @ 2675'. Stretched 4 1/2" csg, free point indicated @ 170'. No casing pulled. WIH to 605' w/deep penetrator gun & perforated 4 1/2" & 7" csg w/4 JSPF @ 605'. POH w/perforator. Installed 4 1/2" swage & pumped in 3 BFW. RIH w/4 1/2" cmt retr, set retr @ 400'. Pumped 85 sx Cl C cmt thru retr & perfs @ 605', no squeeze. PO of retr & spotted 4 sx Cl C cmt on top of retr (50' plug). Pulled up hole & spotted 5 sx Cl C cmt @ surface, installed regulation dry hole marker. Clean & leveled location in accordance w/USGS & DLM stipulations. P&A eff 3/24/76. Final Report. Your office to be notified when location is ready for inspection.

RECEIVED

AUG 12 1976

U.S.G.
MEDIA, OFFICE

18. I hereby certify that the foregoing is true and correct

SIGNED

TITLE Dist. Drlg. Supv.

DATE 4/1/76

(This space for Federal or State office use)

APPROVED BY

TITLE

DATE

CONDITIONS OF APPROVAL, IF ANY:

*See Instructions on Reverse Side