	_			Ċ	py W 51	
(May 1963) DEPA	UN EDSTATES ARTMENT OF THE INTER	SCBMIT IN TRIE Other instruction. verse side)	ATE•	Form approv Budget Burer 5. LEASE DESIGNATION	eu. au No. 42–R1424	
GEOLOGICAL SURVEY			,	LC 029395 (b)		
(Do not use this form for	PLICATION FOR PERMIT—" for such	hack to a different magazzaiz		6. IF INDIAN, ALLOTTEI	E OR TRIBE NAME	
OIL X GAS OTE	HER			7. UNIT AGREEMENT NA	21.0	
2. NAME OF OPERATOR		MAR 2 9 1976		8. FARM OR LEASE NAM	(E	
Atlantic Richfield Company				Turner "B"		
3. ADDRESS OF OPERATOR P. O. Box 1710, Hobbs, New Mexico 88240 ARTESIA, OFFICE				9. WELL NO. 14		
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.* See also space 17 below.)				10. FIELD AND POOL, OR WILDCAT		
At surface				Fren Seven Rivers		
660' FSL & 1980' FWL (Unit Letter N)				11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA		
				20-17S-31E		
14. PERMIT NO.	15. ELEVATIONS (Show whether D	F, RT, GR, etc.)		12. COUNTY OR PARISH		
	3667' DF			Eddy	N.M.	
16. Chec	k Appropriate Box To Indicate 1	Nature of Notice, Repo	t, or O	ther Data	•	
NOTICE OF	INTENTION TO:		BUBSEQUI	ENT REPORT OF:		
TEST WATER SHUT-OFF	PULL OR ALTER CASING	WATER SHUT-OFF		REPAIRING W		
SHOOT OR ACIDIZE	MULTIPLE COMPLETE	FRACTURE TREATMEN		ALTERING CA		
REPAIR WELL	CHANGE PLANS	(Other) Plu	L	1	<u>X</u>	
(Other)		(Note: Report Completion or	results o	s of multiple completion on Well pletion Report and Log form.)		
17. DESCRIBE PROPOSED OR COMPLETE proposed work. If well is a nent to this work.) *	ED OPERATIONS (Clearly state all pertiner directionally drilled, give subsurface locs	nt details, and give pertinen ations and measured and true	t dates, l	including estimated date depths for all markers	e of starting any and zones perti-	
Rigged up on 3/15/	76, installed BOP. POH 50'. Spotted 35 sx Cl 1	w/69 jts 2-3/8"	OD EU	E tbg. WIH w/	5½" CIBP	
Stretched 51 csg	free point indicated @	R40° WIH w/iet	cutte	or on W. & cut	5 ¹ " csg @	
	covered. Circ hole w/he					
	706' (100' plug 850-950					
_	' plug 506-606'). Spots					
	e marker. P&A eff 3/16/					
-	lations. Your office to	be notified whe	n loca	ation is ready	for	
inspection.				•		
				*		
		•		. 15	D	
		•		CENT		
			•	RECENT	76	