

Cory & SF

(July 1966)

DEPARTMENT OF THE INTERIOR  
GEOLOGICAL SURVEY

DATE: (Other instructions on reverse side)

Budget Approved.  
Budget Bureau No. 42-R1424.

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use "APPLICATION FOR PERMIT—" for such proposals.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>		7. UNIT AGREEMENT NAME	
2. NAME OF OPERATOR Atlantic Richfield Company		8. FARM OR LEASE NAME Turner "B"	
3. ADDRESS OF OPERATOR P. O. Box 1710, Hobbs, New Mexico 88240		9. WELL NO. 14	
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements. See also space 17 below.) At surface 660' FSL & 1980' FWL (Unit Letter N)		10. FIELD AND POOL, OR WILDCAT Fren Seven Rivers	
14. PERMIT NO.		11. SEC., T., E., M., OR BLK. AND SURVEY OR AREA 20-17S-31E	
15. ELEVATIONS (Show whether DF, RT, GR, etc.) 3667' DF		12. COUNTY OR PARISH Eddy	
		13. STATE N.M.	

RECEIVED

AUG 26 1976

D. C. C.  
ARTESIA, OFFICE

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

SUBSEQUENT REPORT OF:

TEST WATER SHUT-OFF <input type="checkbox"/>	PULL OR ALTER CASING <input type="checkbox"/>	WATER SHUT-OFF <input type="checkbox"/>	REPAIRING WELL <input type="checkbox"/>
FRACTURE TREAT <input type="checkbox"/>	MULTIPLE COMPLETE <input type="checkbox"/>	FRACTURE TREATMENT <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
SHOOT OR ACIDIZE <input type="checkbox"/>	ABANDON* <input type="checkbox"/>	SHOOTING OR ACIDIZING <input type="checkbox"/>	ABANDONMENT* <input type="checkbox"/>
REPAIR WELL <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	(Other) Plug & Abandon <input checked="" type="checkbox"/>	

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.) \*

Rigged up on 3/15/76, installed BOP. POH w/69 jts 2-3/8" OD EUE tbg. WIH w/5 1/2" CIBP on WL, set BP @ 1850'. Spotted 35 sx Cl H cmt on top of BP. Top of cmt plug @ 1750'. Stretched 5 1/2" csg, free point indicated @ 840'. WIH w/jet cutter on WL & cut 5 1/2" csg @ 700'. Pulled & recovered. Circ hole w/heavy gelled mud. Spotted 35sx Cl H cmt across 5 1/2" OD csg stub @ 706' (100' plug 850-950'). Spotted 35 sx Cl H cmt across 7" csg shoe & top of salt (100' plug 506-606'). Spotted 10 sx Cl H cmt @ surface. Installed regulation dry hole marker. P&A eff 3/16/76. Cleaned & levelled location in accordance w/USGS & BLM stipulations. Your office to be notified when location is ready for inspection.

RECEIVED  
MAR 26 1976  
U.S. GEOLOGICAL SURVEY  
ARTESIA, NEW MEXICO

18. I hereby certify that the foregoing is true and correct

SIGNED [Signature] TITLE Dist. Drlg. Supv. DATE 3/24/76

(This space for Federal or State office use)

APPROVED BY \_\_\_\_\_ TITLE \_\_\_\_\_ DATE \_\_\_\_\_  
CONDITIONS OF APPROVAL, IF ANY:

[Signature]

\*See Instructions on Reverse Side