

0+5-MMS-Roswell, 1-File, 1-Engr. PS, 1-Foreman-EF, 1-Laura Richardson-Midland

Form 9-331  
Dec. 1973

Form Approved.  
Budget Bureau No. 42-R1424

UNITED STATES  
DEPARTMENT OF THE INTERIOR  
GEOLOGICAL SURVEY

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use Form 9-331-C for such proposals.)

1. oil ☐ well gas ☐ well other ☒ Injection well
2. NAME OF OPERATOR  
Getty Oil Company /
3. ADDRESS OF OPERATOR  
P.O. Box 730 Hobbs, NM 88240
4. LOCATION OF WELL (REPORT LOCATION CLEARLY. See space 17 below.)  
AT SURFACE: Unit ltr. F, 1980 FNL & 1980 FWL  
AT TOP PROD. INTERVAL:  
AT TOTAL DEPTH:
16. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

- REQUEST FOR APPROVAL TO: SUBSEQUENT REPORT OF:
- |                      |                                     |                          |
|----------------------|-------------------------------------|--------------------------|
| TEST WATER SHUT-OFF  | <input checked="" type="checkbox"/> | <input type="checkbox"/> |
| FRACTURE TREAT       | <input type="checkbox"/>            | <input type="checkbox"/> |
| SHOOT OR ACIDIZE     | <input type="checkbox"/>            | <input type="checkbox"/> |
| REPAIR WELL          | <input type="checkbox"/>            | <input type="checkbox"/> |
| PULL OR ALTER CASING | <input type="checkbox"/>            | <input type="checkbox"/> |
| MULTIPLE COMPLETE    | <input type="checkbox"/>            | <input type="checkbox"/> |
| CHANGE ZONES         | <input type="checkbox"/>            | <input type="checkbox"/> |
| ABANDON*             | <input type="checkbox"/>            | <input type="checkbox"/> |
- (other) \_\_\_\_\_

5. LEASE  
LC-029420 (b)
6. IF INDIAN, ALLOTTEE OR TRIBE NAME
7. UNIT AGREEMENT NAME  
Skelly Unit
8. FARM OR LEASE NAME  
Skelly Unit
9. WELL NO.  
64
10. FIELD OR WILDCAT NAME  
Grayburg Jackson
11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA  
21 T17S, R31E
12. COUNTY OR PARISH  
Eddy
13. STATE  
NM
14. API NO.
15. ELEVATIONS (SHOW DF, KDB, AND WD)  
3767' DF

(NOTE: Report results of multiple completion or zone change on Form 9-330.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)\*

1. Rig up pulling unit.
2. Install BOP.
3. Pull out of hole w/pkr & tbq.
4. Run in hole with bridge plug & pkr.
5. Locate hole in pipe.
6. Squeeze hole with cement.
7. Drill out cement.
8. Run in hole with pkr & place back on injection.

RECEIVED

AUG 25 1982

OIL & GAS  
MINERALS MGMT. SERVICE  
ROSWELL, NEW MEXICO

Subsurface Safety Valve: Manu. and Type \_\_\_\_\_ Set @ \_\_\_\_\_ Ft.

18. I hereby certify that the foregoing is true and correct

SIGNED Dale R. Crockett TITLE Area Superintendent DATE August 25, 1982

APPROVED BY PETER W. CHESTER (This space for Federal or State office use) DATE \_\_\_\_\_

CONDITIONS OF APPROVAL, IF ANY:

pas  
SJD

AUG 30 1982

FOR  
JAMES A. OILHAM \*See Instructions on Reverse Side  
DISTRICT SUPERVISOR