NM OIL CONS COMMISSION

Drawer DD

Form 3160-5 (June 1990)

1. Type of Well

2. Name of Operator

Oil Gas Well

3. Address and Telephone No.

Texaco E&P Inc.

UNITED STATES DEPARTMENT OF THE INTERIOR **BUREAU OF LAND MANAGEMENT**

Artesia, NM 88210

ARTESIA, OFFICE

FORM APPROVED Budget Bureau No. 1004-0135

Expires: March 31, 1993 5. Lease Designation and Serial No.

LC-029420-B 6. If Indian, Allottee or Tribe Name

SUNDRY NOTICES AND REPORTS ON WELLS

Do not use this form for proposals to drill or to deepen or reentry to a different reservoir. Use "APPLICATION FOR PERMIT—" for such proposals

SUBMIT IN TRIPLICATE

7. If Unit or CA, Agreement Designation Skelly Unit 8. Well Name and No. g 9. API Well No. 30-015-05321

P.O. Box 3109 Midland, Tx 79702 4. Location of Well (Footage, Sec., T., R., M., or Survey Description)

Other

FNL & 1980 FEL

Sec. 21, T-17s, R-31E

Fren 7-Rivers 11. County or Parish, State

10. Field and Pool, or Exploratory Area

			Eddy NM		
12.	CHECK APPROPRIATE BOX(s) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA				
	TYPE OF SUBMISSION	TYPE OF ACTION			
	X Notice of Intent	Abandonment	Change of Plans		
	Subsequent Report	Recompletion Plugging Back	New Construction Non-Routine Fracturing		
	Final Abandonment Notice	Casing Repair Altering Casing	Water Shut-Off Conversion to Injection		
:		L_J Other	Dispose Water (Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)		

Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

- Notify BLM 48 hours prior to moving in to plug well. 1.
- MIRU Pool W.D. Unit & P&R equipment.
- Pickup 2 3/8" workstring TIH to @ 2000' tag plug. 3.
- Load hole w/9.5# gal. plug mud.
- Spot 40 sx cmt plug f/1690-1555 (Yates)
- 6. POH & spot 226 sx cmt plug
- 1500-550 (Salt section & shoe plug)
- POH & spot 25 sx cmt plug 492-392
- Laydown tub & spot 20 sx plug @ 30-surface. Cut off well head @ 3'below ground level & cap well. Install 3" marker post w/well discription & plugging date.
- 9. Rig down W.D. Unit & P&A Equipment. Clean up location. (see well stamatics & prior W.D. reports included)

14. I hereby certify that the foregoing is true and correct		-	
Signed Ry Ward Zell	Title Operations Engineer	Date	8-23-94
(This space for Federal or State office use) (ORIG. SGD.) JOE G. LAPA Approved by Conditions of approval, if any in Conditions of approximate approxi	Title PETROLEUM ENGINEES	Date	123/94
Approved by Conditions of approval, if any: See attached,	Also, surface plug a min	Vi. miln	50'.