

Form 3160-3
(June 1990)

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

NM OIL CON
Drawer DD
Artesia, NM 88210

FORM APPROVED
Budget Bureau No. 1004-0135
Expires: March 31, 1993

SUNDRY NOTICES AND REPORTS ON WELLS

Do not use this form for proposals to drill or to deepen or reentry to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals

SUBMIT IN TRIPLICATE

1. Type of Well

☒ Oil Well ☐ Gas Well ☐ Other

2. Name of Operator

Texaco E&P Inc.

3. Address and Telephone No.

P.O. Box 730 Hobbs, NM 88240

4. Location of Well (Footage, Sec., T., R., M., or Survey Description)

Unit G 1980 FNL 1980 FEL Sec.21 T-17S R-31E

5. Lease Designation and Serial No.

2C-029420-B

6. If Indian, Allottee or Tribe Name

7. If Unit or CA, Agreement Designation

8. Well Name and No.

Skelly Unit #9

9. API Well No.

30-015-0521 05321

10. Field and Pool, or Exploratory Area

Fren 7-Rivers

11. County or Parish, State

Eddy

12. CHECK APPROPRIATE BOX(s) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

TYPE OF SUBMISSION

- ☐ Notice of Intent
☒ Subsequent Report
☒ Final Abandonment Notice

TYPE OF ACTION

- ☒ Abandonment
☐ Recompletion
☐ Plugging Back
☐ Casing Repair
☐ Altering Casing
☐ Other

- ☐ Change of Plans
☐ New Construction
☐ Non-Routine Fracturing
☐ Water Shut-Off
☐ Conversion to Injection
☐ Dispose Water

(Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

13. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

12-12-94 Notify BLM of intent to plug & abandon well.
12-13-94 RU Pool ND wellhead N.U. BOP. TIH w/tub & tag CIBP @ 2000'.
12-13-94 Mix plug mud 25# per bbl. Salt gel & 9.5# brine & circ. hole.
12-13-94 Spot 40sxs class C cmt. plug from 1690-1555.
12-13-94 POOH to 1500; Spot 226 sxs class C cmt. from 1500-550.
12-13-94 POOH to 492; Spot 25 sxs class C cmt. from 492-392.
12-13-94 POOH to 30; Spot 20 sxs class C cmt. plug from 30-surface.
12-13-94 ND BOP dig out cellar; cut off wellhead; Install dryhole marker w/legal description of well. Clean location. RD pulling unit & plugging equip. move off location.

Approval as to pressure on the well bore.
Liability under bond is retained until
surface restoration is completed.

14. I hereby certify that the foregoing is true and correct

Signed Larry Winn Larry Winn

Title P&A Supervisor (Agent) Pool Co.

Date 12-13-94

(This space for Federal or State official use)

(TORIC SGO) JOE G. LARA

Approved by
Conditions of approval, if any:

Title PETROLEUM ENGINEER

Date 1/27/95