

NM OIL CONS. COMMISSION  
Drawer 10  
Artesia, NM 88200

Form 9-331 O+5-USGS - P.O. Box 1857  
Dec. 1973 Roswell, NM 88201

1 - PWS  
1 - EF, LG

1 - Laura Richardson  
1 - File Budget Bureau No. 42-R1424

UNITED STATES  
DEPARTMENT OF THE INTERIOR  
GEOLOGICAL SURVEY

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use Form 9-331-C for such proposals.)

1. oil well ☒ gas well ☐ other

2. NAME OF OPERATOR  
Getty Oil Company

3. ADDRESS OF OPERATOR  
P.O. Box 730 Hobbs, NM 88240

4. LOCATION OF WELL (REPORT LOCATION CLEARLY. See space 17 below.)  
AT SURFACE: Unit 1 tr. I, 1980 FSL & 660' FEL  
AT TOP PROD. INTERVAL:  
AT TOTAL DEPTH:

16. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

REQUEST FOR APPROVAL TO:

TEST WATER SHUT-OFF ☐

FRACTURE TREAT ☐

SHOOT OR ACIDIZE ☒

REPAIR WELL ☐

PULL OR ALTER CASING ☐

MULTIPLE COMPLETE ☐

CHANGE ZONES ☐

ABANDON\* ☐

(other) ☐

SUBSEQUENT REPORT OF:

☐

☐

☐

☐

☐

☐

☐

☐

☐

(NOTE: Report results of multiple completion or zone change on Form 9-330.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)\*

1. Rig up pulling unit.
2. Install BOP.
3. Pull both strings of rods and tubing.
4. Run BP and packer.
5. Acidize with 6000 gals of 15% NEFE. (2217-2330').
6. Swab load.
7. Revover B.P.
8. Run tubing and rods.
9. Place back on production.

Subsurface Safety Valve: Manu. and Type \_\_\_\_\_ Ft.

18. I hereby certify that the foregoing is true and correct

SIGNED \_\_\_\_\_

Date \_\_\_\_\_

TITLE Area Superintendent DATE October 25, 1982

(This space for Federal or State office use)

APPROVED BY \_\_\_\_\_  
CONDITIONS \_\_\_\_\_

OF APPROVAL, IF ANY:

NOV 10 1982

FOR

JAMES A. GILLHAM  
DISTRICT SUPERVISOR

\*See Instructions on Reverse Side