(SUBMIT IN TRIPLICATE)

H. M. O. C. F. CHY

UNITED STATES

HOOK DEPARTMENT OF THE INTERIOR **GEOLOGICAL SURVEY**

SUNDRY NOTICES AND REPORTS ON WELL

SUBSEQUENT REPORT OF WATER SHUT-OFF
SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING
SUBSEQUENT REPORT OF ALTERING CASING
SUBSEQUENT REPORT OF RE-DRILLING OR REPAIR
SUBSEQUENT REPORT OF ABANDONMENT
SUPPLEMENTARY WELL HISTORY

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

		4000 11	TILE SEE SEALES NOVEMBER 7, 190
Well No. 15 is locate	ed 1660 ft. f	$\{ rom \setminus N \}$ line	and 1480 ft. from E line of sec. 31
NESWE Section 31	17-5	3G-B	No Mo PoMo
(½ Sec. and Sec. No.)	(Twp.)	(Range)	(Meridian)
Less Hills (Field)	(Co	unty or Subdivision)	New Mexico (State or Territory)
The elevation of the derrick			
	DE	TAILS OF W	ORK
(State names of and expected depths to		ow sizes, weights, and d all other important	d lengths of proposed casings; indicate mudding jobs, cemer t proposed work)
- 1 1 2010			Brd 32.75# used HS seeing to 451
Note: This casing w	ne enbeeque	ently pulled	during cementing operations on
I understand that this plan of work Company General Ameri			Geological Survey before operations may be commenced.
Address P. C. Box 416	•		D d1
Loca alle.	em Maxico	-	By Aleen