

Form 3160-5
November 1983)
Formerly 9-331)

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

SUBMIT IN TRIPPLICATE*
(Other instructions on re-
verse side)

Form approved.
Budget Bureau No. 1004-0135
Expires August 31, 1985

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.)

1. OIL WELL ☒ GAS WELL ☐ OTHER ☐		5. LEASE DESIGNATION AND SERIAL NO. LC-028784-C
2. NAME OF OPERATOR Phillips Petroleum Company		6. IF INDIAN, ALLOTTEE OR TRIBE NAME
3. ADDRESS OF OPERATOR 4001 Penbrook St., Odessa, Texas 79762		7. UNIT AGREEMENT NAME
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.* See also space 17 below.) At surface Unit L, 1980' FSL & 660' FWL		8. FARM OR LEASE NAME Keely "C" Federal
14. PERMIT NO. API No. 30-015-05910		9. WELL NO. 15
15. ELEVATIONS (Show whether SP, RT, OR, etc.) 3575' GL		10. FIELD AND POOL, OR WILDCAT Gb/Jackson SR-Q-Gb-SA
		11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA Sec. 26, 17-S, 29-E
		12. COUNTY OR PARISH Eddy
		13. STATE NM

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF

PULL OR ALTER CASING

FRACTURE TREAT

MULTIPLE COMPLETE

SHOOT OR ACIDIZE

ABANDON*

REPAIR WELL

CHANGE PLANS

(Other)

SUBSEQUENT REPORT OF:

WATER SHUT-OFF

FRACTURE TREATMENT

SHOOTING OR ACIDIZING

(Other) Set CIBP & TA wellbore

(NOTE: Report results of multiple completion or Well Completion or Recompletion Report and Log form.)

REPAIRING WELL

ALTERING CASING

ABANDONMENT*

X

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

6-4-92: MI & RU. NU BOP. Release pkr. COOH with tubing and pkr. GIH with 7" scraper to 2460'. COOH. GIH with 7" CIBP to 2422'. Set plug Pull up and circulate packer fluid 94 bbl Tretolite KW 132 and water. Close BOP. Press up on csg. Record press. test. No leakage. Ran chart. Passed BLM req. Release press. COOH with workstring laying down. NU wellhead. T/A complete.

Request permit to TA well for one year.

This Approval of Temporary
Abandonment Expires

APPROVED FOR 12 MONTH PERIOD

ENDING 6/4/93

6/04/93

18. I hereby certify that the foregoing is true and correct

SIGNED

L. M. Sanders
L. M. Sanders

TITLE Supv. Reg. & Proration

DATE 6/5/92

915/368-1488

(This space for Federal or State office use)

APPROVED BY

TITLE

DATE 6-16-92

CONDITIONS OF APPROVAL, IF ANY:

*See Instructions on Reverse Side

