to Appropriate Submit 3 Copies District Office

CONDITIONS OF APPROVAL, IF ANY

State of New Mexico $Ener_{{\bf b}{\it J}},\,Minerals\,\,and\,\,Natural\,\,Resources\,\,Department$

Form C-103

Revised 1-1-89 C/SF

DISTRICT	OH CONCEDIA	TIONEDI	истолт			ox	
<u>DISTRICT I</u> P.O. Box 1980, Hobbs NM 88240		DIL CONSERVATION DIVISION 2040 South Pacheco			WELL API NO.		
DISTRICT II Santa Fe, New Mexico 87505				30-015-06103			
811 South First, Artesia, NM 88210				5. Indicate Type	of Lease STATE	FEE 🗆	
DISTRICT III 1000 Rio Brazos Rd, Aztec, NM 87410				6. State Oil & Ga			
SUNDRY NOTICES AND REPORTS ON WELLS				B-1266			
				100		18.1	
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS).				7. Lease Name o	r Unit Agreement Nar	me	
1. Type Of Well: OIL GAS WELL GAS WELL	OTHER			G J West Coo	p Unit		
2. Name of Operator				8. Well No.			
Mack Energy Corporation				5			
3. Address of Operator P.O. Box 960, Artesia, NM 88211-0960				9. Pool name or Wildcat Grayburg Jackson; 7RVS-QN-GB-SA			
4. Well Location	0900	-		Grayburg Jack	son; /RVS-QN-C	jB-SA	
Unit Letter M: 990	Feet From The S	outh Lir	ne and 99	Po Feet Fro	m The Wes	StLine	
Section 27	Township 17S	Range	29E	NMPM	Eddy	Country	
10. Elevation (Show whether DF, RKB, RT, GR, etc.)				I VIVII IVI		County	
		3654 GR	C) I		_		
	Appropriate Box to Ind	icate Nature o		-			
NOTICE OF INT	ENTION TO:		SOB	SEQUENTI	REPORT OF:		
PERFORM REMEDIAL WORK	PLUG AND ABANDON	REMED	IAL WORK		ALTERING CASIN	NG	
TEMPORARILY ABANDON	CHANGE PLANS	СОММЕ	NCE DRILLING	OPNS.	PLUG AND ABAN	IDONMENT 🔀	
PULL OR ALTER CASING		CASING	TEST AND CE	MENT JOB			
OTHER:		OTHER					
12. Describe Proposed or Completed C	perations (Clearly state all pertin	nent details, and give p	pertinent dates, inc	luding estimated dat	e of starting any propo:	sed	
07/28/1999 Spot 35sx plug @ 2833'	. POH to 2711' & rev. out	1/2 bbl cmt. Circ	. hole w/mud.	& POH. RIH ta	ag plug @ 2715'. J	Pull up hole	
to 708' & shoot 2 squeeze holes. RIH						•	
641'. RIH w/wireline & shoot 2 sque							
Γagged plug @ 239'. Set 60' surface					B. I oli co wait I	1/2 Ins.	
ragged plug (b) 239. Set 00 surface	piug & KD punnig unit. Se	ti Dry Hole Mair	Kei.	_			
				91	01112131475		
				60	8)	,\	
				3456	803	a /	
				23	1 2 2 S	18 19 20 2	
				17	1. 2. 4.	20)	
				/5	E S 1	3/	
		105J 111	· * * ?	000	- 15/V	/	
I hereby certify that the information above is true	and complete to the best of my knowl	edge and belief.		1658	5753525120		
SIGNATURE (Lipsa 1)	Cart	TITLE	Production	n Analyst	DATE	5/3/00	
TYPE OR PRINT NAME	Crissa	D. Carter			TELEPHONE NO. (505)748-1288	
(This space for State Use)							
Oli Della	٤.	1:	10 Rep. 7		8-31	- 2 mm	