

CELEBRATE AT CONGRATULATE FOR ACCOMPLISHMENT OF WELLBORE ON

STATE OF OREGON OIL COMMISSION

Company Martin Yates, III

Farm Name _____ State _____ Well No. 9

Sec. 36 Twp. 17S Range 29E County Eddy

Feet from Line: 1650 N. S. E. 1650 W.

Elevation 3568 Method Machine

Contractor Paton Bros

Spudded 4-16-46 Completed 9-30-46

AMOUNT

CASING & CEMENTING RECORD

Size	Feet	Inches	Sax Cement
8 5/8	490		50
7"	3250		150

ACID RECORD		Gals.	
TA		TG	
TX	470	TSA	
TCA		TGI	
BX	935	TYo	
TY		TAb	
TSR		TPenn	
Top Pay	3289	TQ	2130
		TOrd	

TUBING RECORD

2" 3275

PACKER

SHOOTING RECORD

No. of Quarts	From	To
S/o 2775-80	S/	S/
S/o 3260-684	S/	S/
S/o 3210 L	S/	S/

Date	Location	Date	Notes
4-16-46		JUN 18	TD 3296 Line, Reamer
4-23	W.D. 490X		@ 3200 to run 7"
	400		Bailed 2000
MAY 7	Ø 1765 A	JUN 25	TD 3296 Ø plug
MAY 14	Ø 2290 A	JUL 2	TD 3296 1/2 Prep to treat
MAY 20	Ø 2710 Line	JUL 9	TD 3296 1/2 Prep to acid
MAY 20	Ø 2780 Line		Perf 3286-96 w/400
JUN 4	Ø 3016 Line		attempted 1000 gal treat
JUN 11	Ø 3233 Line		

Cmt across Perfs 3280-46

100' plug Top Quene 2130 - 2030 2180
inside + outside casg

100' plug @ BX 435 - 885-885
inside + outside

100' plug @ TX + 3 1/8" shaw 470' - 450-550
inside + outside

1-23-84 1:50 PM.

Mike -

Nelson Muncy will call you on
this - they want to P&A well -

7" too rather to pull - will
SQZ etc & whatever you
think is necessary -

Les.