

Submit 3 Copies
to Appropriate
District Office

State of New Mexico
Energy, Minerals and Natural Resources Department

Form C-103
Revised 1-1-89

DISTRICT I
P.O. Box 1980, Hobbs NM 88240

DISTRICT II
811 South First, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd, Aztec, NM 87410

OIL CONSERVATION DIVISION
2040 South Pacheco
Santa Fe, New Mexico 87505

WELL AB# NO. 30-025-10317
5. Indicate Type of Lease STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
6. State Oil & Gas Lease No. E-4201
7. Lease Name or Unit Agreement Name Continental E State
8. Well No. 1
9. Pool name or Wildcat Artesia Queen Grayburg SA
10. Elevation (Show whether DF, RKB, RT, GR, etc.) 3654 GR

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"
(FORM C-101) FOR SUCH PROPOSALS).

1. Type Of Well: OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>
2. Name of Operator Mack Energy Corporation
3. Address of Operator P.O. Box 960, Artesia, NM 88211-0960
4. Well Location Unit Letter <u>L</u> : <u>1914</u> Feet From The <u>South</u> Line and <u>401</u> Feet From The <u>West</u> Line Section <u>30</u> Township <u>17S</u> Range <u>29E</u> NMPM <u>Eddy</u> County
10. Elevation (Show whether DF, RKB, RT, GR, etc.) 3654 GR

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data	
NOTICE OF INTENTION TO	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>
OTHER: <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
	CASING TEST AND CEMENT JOB <input type="checkbox"/>
	OTHER <input type="checkbox"/>

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

- Set 5 1/2 CIBP at 2300', cap w/35' cement
- Load hole w/mud
- Perforate 5 1/2 at 621' and squeeze Base of Salt w/50sx cement. WOC and Tag top of cement at 570' Spot 100' cement plug at 8000'
- Perforate 5 1/2 at 574' and squeeze Base of Salt w/75sx cement. WOC and Tag top of cement at 400', this plug will also cover the 8 5/8 shoe
- Perforate 5 1/2 at 50' circulate cement to surface between 5 1/2 & 8 5/8 leaving 5 1/2 full. Set P & A marker.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Crissa D. Carter TITLE Production Clerk DATE 7/2/97

TYPE OR PRINT NAME Crissa D. Carter TELEPHONE NO. (505)748-1288

(This space for State Use)

APPROVED BY ORIGINAL SIGNED BY TIM W. GUM TITLE DISTRICT II SUPERVISOR DATE NOV 20 1997

CONDITIONS OF APPROVAL, IF ANY: