

NO. OF COPIES RECEIVED	4
DISTRIBUTION	
SANTA FE	1
FILE	1
U.S.G.S.	
LAND OFFICE	
OPERATOR	1

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

5a. Indicate Type of Lease
State <input checked="" type="checkbox"/> Fee <input type="checkbox"/>

5. State Oil & Gas Lease No.
B 9563, B 10714, B 1266, B 255, B 514

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.
USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>	7. Unit Agreement Name
2. Name of Operator Tenneco Oil Company	8. Farm or Lease Name G-J West Coop. Unit
3. Address of Operator Box 1031, Midland, Texas 79701	9. Well No. 45
4. Location of Well UNIT LETTER A, 660 FEET FROM THE north LINE AND 660 FEET FROM THE east LINE, SECTION 21 TOWNSHIP 17-S RANGE 29-E NMPM.	10. Field and Pool, or Wildcat Grayburg-Jackson
15. Elevation (Show whether DF, RT, GR, etc.) 3571 RKB	12. County Eddy

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>

SUBSEQUENT REPORT OF:

REMEDIAL WORK <input checked="" type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
CASING TEST AND CEMENT JOBS <input type="checkbox"/>	OTHER <input type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

PROCEDURE:

1. Pulled rods and tubing. Moved off pulling unit.
2. Perforated at 2263' - 2532' w/20 3/8" jets. X
Set retrievable bridge plug and wire line at 2570'.
3. Frac down csg. w/500 gals acid and 50,000 gals gelled water and 75,000# 20-40 sand.
Overflushed w/10 BW.
4. Shut-in over night.
5. Bled off pressure, ran tbgs. w/retrievable head and recovered bridge plug.
6. Ran tbgs. and rods and put on pump.

* 1 hole at each of the following intervals 2263, 68, 94, 98, 2313, 19, 29, 36, 2449, 54
67, 89, 92, 99, 2403, 07, 2510, 15, 21 & 2532

RECEIVED

JUL 10 1967

O. O. C.
ARTESIA, OFFICE

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED J. F. Carnes J. F. Carnes TITLE District Production Engineer DATE 7-6-67

APPROVED BY W. R. Gressett

TITLE OIL & GAS ENGINEER

DATE

CONDITIONS OF APPROVAL, IF ANY: