

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

SUBMIT IN THE
(Other instructions on reverse side)

Form approved.
Budget Bureau No. 42-R1424.

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use "APPLICATION FOR PERMIT—" for such proposals.)

1. OIL WELL ☐ GAS WELL ☐ OTHER ☒ **DRY HOLE**

2. NAME OF OPERATOR **Artesia Production Company**

3. ADDRESS OF OPERATOR **Box 10, Artesia, N.M. 88240**

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements. See also space 17 below.)
At surface
1380' FNL x 1368' FEL, Sec. 11 (Unit 6, SW 1/4 NE 1/4)

14. PERMIT NO. 15. ELEVATIONS (Show whether DF, RT, GR, etc.)
3647' R.D.B.

5. LEASE DENOMINATION AND SERIAL NO. **NM-018732**

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

7. UNIT AGREEMENT NAME

8. FARM OR LEASE NAME **Artesia "A" Federal**

9. WELL NO.

10. FIELD AND POOL OR WILDCAT **Artesia**

11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA

12. COUNTY OR PARISH **EDDY** 13. STATE **N.M.**

RECEIVED
OCT 29 1971
O. C. C.
ARTESIA, OFFICE

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
TEST WATER SHUT-OFF ☐	PULL OR ALTER CASING ☐	WATER SHUT-OFF ☒	REPAIRING WELL ☐
FRACTURE TREAT ☐	MULTIPLE COMPLETE ☐	FRACTURE TREATMENT ☐	ALTERING CASING ☐
SHOOT OR ACIDIZE ☐	ABANDON* ☒	SHOOTING OR ACIDIZING ☐	ABANDONMENT* ☐
REPAIR WELL ☐	CHANGE PLANS ☐	(Other) Complete Abandonment ☒	

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)

On 10-17-71, 4 1/2" OD 9.5# Casing was set @ 2570' (TD) w/ 175 SX.
Incor med. Tested casing w/ 2000 psi for 30 min. Test O.K.
After WOC appx 48 hours, perforated intervals 2489-99 w/ 25PF
and 2499-2502 w/ 415PF. Fraced w/ 25,000 gal gel
brine + 37,500# sand. Never recovered load. No
show of oil or gas. Dry Hole -
Propose to P & A as follows:

Spot 1524 cement plug across perfs; cut & pull 4 1/2" from
appx 2550'; 25SX plug in + cut of 4 1/2" stub; 25 SX @
10' below @ 1030'; 25 SX in + cut of 8 1/2" CSA 400'; 10 SX @
surface and set P & A marker. Make final cleanup
and restore to contour.

TD - 2570' 4 1/2" CSA 2570 w/ 175 SX
K - 2550' 8 1/2" CSA 400' - circ.

RECEIVED
OCT 28 1971
U. S. GEOLOGICAL SURVEY
ARTESIA, NEW MEXICO

I hereby certify that the foregoing is true and correct

SIGNED _____ TITLE **AREA SUPERINTENDENT** DATE **OCT 27 1971**

(This space for Federal or State office use)

APPROVED BY _____
COMMISSIONER OF GEOL. & MIN. IF ANY:

TITLE _____ DATE _____

2-4 - USES - ACT
1 - ACS
1 - SUSP
1 - RRY

APPROVED
OCT 28 1971
R. L. BEEKMAN
ACTING DISTRICT ENGINEER

See Instructions on Reverse Side

