

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

SUBMIT IN TRIPLICATE*
(Other instructions on re-
verse side)

Form approved
Budget Bureau No. 1004-0135
Expires August 31, 1985

1. LEASE DESIGNATION AND SERIAL NO.

LC-028784-93-B

2. IF NEGAN, ALLOTTEE OR TRIBE NAME

3. SURVEY AGREEMENT NAME

4. NAME OR LEASE NAME

Burch "BB" Federal

5. WELL NO.

25

6. FIELD AND POOL, OR WILDCAT

Gb/Jackson SR-Q-Gb-SA

7. SEC. T., R., N., OR BLK. AND
SUBDIVISION OR AREA

Sec. 18, 17-S, 30-E

8. COUNTY OR PARISH

Eddy

9. STATE

NM

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.)

1.

OIL WELL ☒ GAS WELL ☐ OTHER ☐

2. NAME OF OPERATOR

Phillips Petroleum Company

3. ADDRESS OF OPERATOR

4001 Penbrook Street, Odessa, Texas 79762

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.*
(See also space 17 below.)
At surface

Unit C, 660' FNL, 1893' FWL

10. PERMIT NO.

API No. 30-015-20562

11. ELEVATIONS (Show whether SP, TP, or, etc.)

3658' RKB - 3648' GL

16.

Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF

FRACTURE TREAT

SHOOT OR ACIDIZE

REPAIR WELL

(Other)

PLUG OR ALTER CASING

MULTIPLE COMPLETION

ABANDON*

CHANGE PLANS

SUBSEQUENT REPORT OF:

WATER SHUT-OFF

FRACTURE TREATMENT

SHOOTING OR ACIDIZING

(Other) Set CIBP & TA wellbore

REPAIRING WELL

ALTERING CASING

ABANDONMENT*

(Note: Report results of multiple completion on Well
Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any
proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones perti-
nent to this work.)*

3-30-92:

GIH with 3-7/8 bit and scraper on 2-3/8
workstring. Ran scraper to 2600'. COOH and run in with CIBP. Set
plug at 2468'. Come up 5 ft. and circulate wellbore w/37 bbl KW132
mix with fresh water. Install recorder in system, press up casing
to 500# for 15 min. Held OK. COOH w/workstring. Don Early w/BPM
witness test. Well temp drop from report. Request permit to TA
well for one year.

APPROVED FOR 12 MONTH PERIOD

ENDING 3/29/93

18. I hereby certify that the foregoing is true and correct

SIGNED

[Signature]
R. Sanders

TITLE

Supv., Reg/Proration

DATE

04-01-92

(This space for Federal or State office use)

APPROVED BY

CONDITIONS OF APPROVAL, IF ANY:


PETROLEUM ENGINEER

(915) 368-1488

DATE

4-8-92

*See Instructions on Reverse Side



RECEIVED
APR 1 1972