

CISF
gp

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240

OIL CONSERVATION DIVISION

2040 Pacheco St.
Santa Fe, NM 87505

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

WELL API NO. 30-015-24143
Indicate Type of Lease STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
State Oil & Gas Lease No. E-742
Lease Name or Unit Agreement Name State S 19
Well No. 3
Pool name or Wildcat Empire Abo

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

Type of Well:
 OIL WELL GAS WELL OTHER

Name of Operator
Mack Energy Corporation

Address of Operator
P.O. Box 960, Artesia, NM 88211-0960

Well Location
 Unit Letter J : 1980 Feet From The South Line and 1980 Feet From The East Line
19 Section 17S Township 29E Range NMPM Eddy County

Elevation (Show whether DF, RKB, RT, GR, etc.)
3668GL

11 Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>
OTHER: <input type="checkbox"/>	CASING TEST AND CEMENT JOB <input type="checkbox"/>
	OTHER: <input type="checkbox"/>
	PLUG AND ABANDON <input checked="" type="checkbox"/>
	PLUG AND ANBANDONMENT <input type="checkbox"/>
	CHANGE PLANS <input type="checkbox"/>

Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Notify 24Hrs. Before starting

- MIRU RIH tag CIBP @ 7065 spot 35' cmt on top
- Cut & pull % 1/2 casing from 6200' * 25' cement plug @ 6200' *6200' 600'*
- RIH spot 100' plug 50' in 50' out stub woc tag
- POH spot 100' plug @ 3970 (Glorieta @ 3918) *min. cement plug 3918'*
- POH spot 100' plug @ 2650 (9 5/8 shoe @ 2600') woc tag
- POH spot 100' plug @ 900 (salt)
- POH spot 100' plug @ 725 (13 3/8 shoe @ 675') TAG
- POH spot 60' plug @ surface
- cut off well head install dry hole marker



* Brine gel between cement plugs.

Notify N.M.O.C.D. to witness plugging operations.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Wayne Brooks TITLE Agent DATE 01-09-01

TYPE OR PRINT NAME Wayne Brooks TELEPHONE NO. 915 5807161

(This space for State Use)

APPROVED BY Mike Stillfield TITLE Field Rep. II DATE 1/11/2001

CONDITIONS OF APPROVAL, IF ANY: