

UNITED STATES DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT
NEW OIL COLS. COMMISSION

SUBMIT IN TRIP DATE*
(Other instruction) re-

Expires August 31, 1985 *cbf*

5. LEASE DESIGNATION AND SERIAL NO.

NM-010907-A

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

7. UNIT AGREEMENT NAME

8. FARM OR LEASE NAME

Featherstone

9. WELL NO.

1

10. FIELD AND POOL, OR WILDCAT

Turkey Track SR On Grbg

11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA

Sec. 34-T18S-R29E

12. COUNTY OR PARISH

Eddy

13. STATE

N.M.

SUNDRY NOTICES AND REPORTS ON WELLS 88210

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use "APPLICATION FOR PERMIT—" for such proposals.)

RECEIVED BY
MAY 01 1986
O. C. D.
ARTESIA, OFFICE

1. OIL WELL GAS WELL OTHER WIW

2. NAME OF OPERATOR
Marbob Energy Corporation

3. ADDRESS OF OPERATOR
P.O. Drawer 217, Artesia, N.M. 88210

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.* See also space 17 below.)
At surface

990 FNL 2310 FEL

14. PERMIT NO.

15. ELEVATIONS (Show whether DF, RT, GR, etc.)

3430' GR

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

SUBSEQUENT REPORT OF:

TEST WATER SHUT-OFF

PULL OR ALTER CASING

WATER SHUT-OFF

REPAIRING WELL

FRACTURE TREAT

MULTIPLE COMPLETE

FRACTURE TREATMENT

ALTERING CASING

SHOOT OR ACIDIZE

ABANDON*

SHOOTING OR ACIDIZING

ABANDONMENT*

REPAIR WELL

CHANGE PLANS

(Other) _____

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

We propose to plug and abandon as follows: Set cement plug from 2100' to 1850'; tag; shoot casing off @ 1800'; set 100' plug in and out of stub; tag; set 100' plug @ 970' covering base of salt; tag; set 100' plug @ 390' covering top of salt & shoe-8 5/8"; tag; set 50' plug @ surface; install dry hole marker.

18. I hereby certify that the foregoing is true and correct

SIGNED

Carroll J. Purcell

TITLE

Production Clerk

DATE

4/22/86

(This space for Federal or State office use)

APPROVED BY

TITLE

DATE

4/29/86

CONDITIONS OF APPROVAL, IF ANY:

*See Instructions on Reverse Side

COMPANY WARRIOR
LEASE & WELL NO. Fentherstone
FORMATION _____
COUNTY & STATE _____



Completion Supervisor

(505) 748-3303

P. O. Drawer 217

Artesia, N.M.

88211-0217

marbob
energy corporation

8 5/8 24# @ 341' c/25 SAY

Top Salt 331'
BASE Salt 917'
T7 RIVERS 1200'
Top Queen 1800'

S/O 760-775 * 7 RIVERS
S/O 975-994 * 7 RIVERS
S/O 2096-2105

OH 2097-2108
FRAC 32,000 GAL @ 39,000# SAND

Converted to Inj 6-15-71

5 1/2 14# @ 2097' c/30 SAY

1947
1882
1947
65

100% 1882
70% 1947

PROPOSAL

P&A as follows set 100' Plug
@ 2100' Tag Run free Point
shot casing off @ 1900' set
100' Plug in & out off stub
set 100' Plug @ 970' Tag
set 100' Plug @ 380' Tag
15sx Plug @ surface

TD 2105