

Copy to S. F.

NMOCC COPY

Form 9-331
(May 1963)

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

SUBMIT IN TRIPLICATE*
(Other instructions on re-
verse side)

Form approved.
Budget Bureau No. 42-R1424.

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.)

1. OIL WELL <input type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input checked="" type="checkbox"/> Injector		RECEIVED	
2. NAME OF OPERATOR Getty Oil Company		FEB 22 1978	
3. ADDRESS OF OPERATOR P.O. Box 730 Hobbs, New Mexico 88240		D.C.C. ARTESIA, OFFICE	
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements. See also space 17 below.) At surface 660 FNL & 660 FWL		7. UNIT AGREEMENT NAME Skelly Unit	
14. PERMIT NO.		8. FARM OR LEASE NAME	
15. ELEVATIONS (Show whether DF, RT, GR, etc.) 3771 D.F.		9. WELL NO. 91	
16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data		10. FIELD AND POOL, OR WILDCAT Grayburg Jackson (G.S.)	
17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)		11. SEC., T., R., M., OR BLM. AND SURVEY OR AREA 28-17-31	
18. COUNTY OR PARISH Eddy		13. STATE N.M.	

NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
TEST WATER SHUT-OFF <input type="checkbox"/>	PULL OR ALTER CASING <input type="checkbox"/>	WATER SHUT-OFF <input type="checkbox"/>	REPAIRING WELL <input type="checkbox"/>
FRACTURE TREAT <input type="checkbox"/>	MULTIPLE COMPLETE <input type="checkbox"/>	FRACTURE TREATMENT <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
SHOOT OR ACIDIZE <input type="checkbox"/>	ABANDON* <input type="checkbox"/>	SHOOTING OR ACIDIZING <input type="checkbox"/>	ABANDONMENT* <input type="checkbox"/>
REPAIR WELL <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	(Other) <input type="checkbox"/>	(Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)
(Other) Bring cement above 7-Rivers XX			

- (1) Pull tubing and packer.
- (2) Run Cement Bond Log.
- (3) Perforate and bring cement above 7-Rivers.
- (4) Run Temperature Survey.
- (5) Drill out cement.
- (6) Rerun tubing and packer.
- (7) Place well back on injection.

RECEIVED
FEB 16 1978
U.S. GEOLOGICAL SURVEY
ARTESIA, NEW MEXICO

18. I hereby certify that the foregoing is true and correct			
SIGNED	<i>Don J. Beahm</i>	TITLE	Area Superintendent
DATE 2-14-78			
(This space for Federal or State office use)			
APPROVED BY	<i>Lee H. Lora</i>	TITLE	ACTING DISTRICT ENGINEER
DATE FEB 22 1978			