

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
TITLE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

IL CONSERVATION DIVISION

P. O. BOX 2088

SANTA FE, NEW MEXICO 87501

MAY 26 1986

O. C. D.

ARTESIA, N.M.

Form C-163
Revised 10-1-78

5a. Indicate Type of Lease	State <input checked="" type="checkbox"/> Fee <input type="checkbox"/>
5. State Oil & Gas Lease No.	B-7717

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER- <input checked="" type="checkbox"/> Water Injection Well	7. Unit Agreement Name
2. Name of Operator Herman J. Ledbetter	8. Farm or Lease Name Leonard State
3. Address of Operator P. O. Box 5879, Abilene, Texas 79605	9. Well No. 1
4. Location of Well UNIT LETTER 0 330 FEET FROM THE South LINE AND 1650 FEET FROM THE East LINE, SECTION 1 TOWNSHIP 19S RANGE 29E NMPM.	10. Field and Pool, or subcat East Turkey Track Queen
15. Elevation (Show whether DF, RT, GR, etc.) 3402	12. County Eddy

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data
NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK <input checked="" type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>

SUBSEQUENT REPORT OF:

REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
CASING TEST AND CEMENT JOBS <input type="checkbox"/>	OTHER <input type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103.

- Hook up cementer to oil string and squeeze down casing with Bradenhead open. When cement returns to surface via annulus between oil string and surface pipe, close in bradenhead and continue squeeze.
- Let cement set.
- Drill out cement in casing and test.

Originals Returned 6-5-86

8. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED Herman J. Ledbetter TITLE Operator DATE 5-20-86

APPROVED BY _____ TITLE _____ DATE _____

CONDITIONS OF APPROVAL, IF ANY: