IEXICO OIL CONSERVATION COM ISSIC

Santa Fe, New Mexico

MISCELLANEOUS NOTICES

triplicate to the Oil Commission or its proper agent before the work

	notice by checking below:	
OTICE OF INTENTION TO TEST CASING SHUT-OFF	NOTICE OF INTENTION TO SHOOT OR CHEMICALLY TREAT WELL	
OTICE OF INTENTION TO CHANGE PLANS	NOTICE OF INTENTION TO PULL OR OTHERWISE ALTER CASING	
OTICE OF INTENTION TO REPAIR WELL		
OTICE OF INTENTION TO DEEPEN WELL	NOTICE OF INTENTION TO PLUG WELL	X
Hobbs, New	Mexico January 1	1940
OIL CONSERVATION COMMISSION, Santa Fe, New Mexico. Gentlemen: Following is a notice of intention to do certain work a Henry Swift State		
Company or Operator Lease of Sec. 20, T. 19, R. 29	ar ar ar Wildoct	774.14
	, N. M. P. M., 1224020	F1610
Eddy County.		
	ed and dumped 5 sacks of Cament.	
Filled Hole with Mud to 385 and put		th
Filled Hole with Mud to 385 and put Put in 10 Sacks of Cement. Filled Ho Rock On Cement with 4" for Marker.	bridge in easing back to 350. ole with Mud to top. Filled Cellar wi	
Filled Hole with Mud to 385 and put Put in 10 Sacks of Coment. Filled Ho Rock On Coment with 4" for Marker. JAN 11 140	bridge in easing back to 350. ole with Mud to top. Filled Cellar wi	
Filled Hole with Mud to 385 and put Put in 10 Sacks of Coment. Filled Ho Rock On Coment with 4" for Marker. JAN 11 140	bridge in easing back to 350. ole with Mud to top. Filled Cellar wi	
Filled Hole with Mud to 385 and put Put in 10 Sacks of Coment. Filled Ho Rock On Coment with 4" for Marker. JAN 11 140	Deridge in casing back to 350. The with Mud to top. Filled Cellar with Mud to top. Filled Cellar with Mud to top. Company or Operator By C. C. Company or Operator	
Filled Hole with Mud to 385 and put Put in 10 Sacks of Coment. Filled Ho Rock On Coment with 4" for Marker. JAN 11 140	bridge in easing back to 350. ole with Mud to top. Filled Cellar wi	
Filled Hole with Mud to 385 and put Put in 10 Sacks of Cement. Filled Ho Rock On Cement with 4" for Marker.	Deridge in casing back to 350. The with Mud to top. Filled Cellar with Mud to top. Filled Ce	to
Filled Hole with Mud to 385 and put Put in 10 Sacks of Cement. Filled Ho Rock On Cement with 4" for Marker. Approved	Deridge in easing back to 350. The with Mud to top. Filled Cellar with Mud to top. Filled Ce	to