

N. M. O. C. C. COPY  
UNITED STATES  
DEPARTMENT OF THE INTERIOR  
GEOLOGICAL SURVEYSUBMIT IN TRIPLICATE\*  
(Other instr. on re-  
verse side)Form approved.  
Budget Bureau No. 42-R1421  
5. LEASE DESIGNATION AND SERIAL NO.

LC 029388(b)

## SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.  
Use "APPLICATION FOR PERMIT—" for such proposals.)

1. OIL WELL <input type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input checked="" type="checkbox"/> WIW		6. IF INDIAN, ALLOTTEE OR TRIBE NAME	
2. NAME OF OPERATOR Atlantic Richfield Company		7. UNIT AGREEMENT NAME	
3. ADDRESS OF OPERATOR P. O. Box 1978, Roswell, New Mexico 88201		8. FARM OR LEASE NAME Johnson Federal	
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.* See also space 17 below.) At surface 660' FSL & 660' FEL (Unit letter P)		9. WELL NO. 1	
14. PERMIT NO.		10. FIELD AND POOL, OR WILDCAT Shugart	
15. ELEVATIONS (Show whether DF, RT, GR, etc.) 3742' DF		11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA Sec. 11, T18S, R31E	
		12. COUNTY OR PARISH Eddy	
		13. STATE N.M.	

## 16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

## NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF

FRACTURE TREAT

SHOOT OR ACIDIZE

REPAIR WELL

(Other)

PULL OR ALTER CASING

MULTIPLE COMPLETION

ABANDON\*

CHANGE PLANS

X

## SUBSEQUENT REPORT OF:

WATER SHUT-OFF

FRACTURE TREATMENT

SHOOTING OR ACIDIZING

(Other)

REPAIRING WELL

ALTERING CASING

ABANDONMENT\*

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)\*

This well was converted to water injection on November 9, 1965. This portion of the Swearingen waterflood is watered out and no longer economical to operate. We propose to P & A as follows:

Spot 30 sk cement plug in and out of 7" shoe 3347'.  
Cut off and pull 7" casing from free point.

Spot these cement plugs:

30 sx in and out of 7" stub

30 sx across 8-5/8" casing shoe at 993'.

10 sx in top of well

9#/gal salt gel mud will be used to spot all cement plugs. 8-5/8" casing string will remain intact. Dry hole marker will be installed and location cleared and levelled.

18. I hereby certify that the foregoing is true and correct

SIGNED

(This space for Federal or State office use)

APPROVED BY  
CONDITIONS OF APPROVAL, IF ANY:

TITLE

Dist. Drlg. Supervisor

DATE

6-1-70

TITLE

DATE