Form 3160-5 June 1990)		NITED STATES ENT OF THE INTERIC	8210 Artesia, NM R	FORM APPROVED Budget Bureau No. 1004-0135
		LAND MANAGEME		Expires: March 31, 1993 5. Lease Designation and Serial No.
SI	INDRY NOTICE	S AND REPORTS OF	N WELLC	NM10190
Do not use this form	for proposals to c		entry to a different reser	6. If Indian. Allonce or Tribe Name VOIT.
SUBMIT IN TRIPLICATE				7. If Unit or CA. Agreement Designation 14-08-001-11572
I. Type of Well Oil Gas Well Well	)	7	JUI 21.94	
Well     Well     Well     Name of Operator	Other	/	0. C. D.	8. Well Name and No.
Devon Energy Cor	poration (Nev	ada) 🖌	し、し、D. ASYNETAL OFFICE	East Shugart Unit # 2
Address and Telephone No. 20 N. Broadway.	Suite 100 Or	C, OK 73102-826		30-015- 05693
			0 405/235-3611	10. Field and Pool, or Exploratory Area
Location of Well (Footage, Sec., T., R., M., or Survey Description)				Shugart (Y-SR-Q-G)
2310' FSL & 1650	0' FWL, Sec. 3	35-T18S-R31E, Uni	tк	11. County or Parish, State Eddy, NM
CHECK APPI	ROPRIATE BOX	S) TO INDICATE NA	TURE OF NOTICE BE	
TYPE OF SUBM	CHECK APPROPRIATE BOX(s) TO INDICATE NATURE OF NOTICE, REPORT TYPE OF SUBMISSION TYPE OF ACTION			
Notice of Intent		Ainada	Pinest	Change of Plans
_		Recom		New Construction
Subsequent Bon				
Subsequent Repo	prt		-	Non-Routine Fracturing
Final Abandonm			Ropair	Water Shut-Off
Final Abandorum	ent Notice	Casing Abarian Coher	Repair 5 Caing run integrity test	Water Shut-Off
Final Abandorum	(1) Rig up (2) Load ca	Pertinent details, and give pertinent depths for all merians and zone pump truck on casing using with water and	Repair s Casing run integrity test an dates, including estimated date of so pertinent to this work.)* g. pressure test to 500 psi	for 30 mins.
Final Abandorum	(1) Rig up (2) Load ca	Cosing Aburing X Other pertinent details, and give pertine depths for all markers and zone	Repair s Casing run integrity test an dates, including estimated date of so pertinent to this work.)* g. pressure test to 500 psi	for 30 mins.
Final Abandorum	ent Notice Operations (Clearly state all d measured and true vertica (1) Rig up (2) Load ca The BLM will f	pertinent details, and give pertinent depths for all markers and zone pump truck on casing asing with water and poe notified 24 hours p	Repair s Casing run integrity test and dates, including estimated date of an pertinent to this work.)* g. pressure test to 500 psi prior to testing.	for 30 mins.
Final Abandonan Describe Proposed or Completed ( give subsurface locations and hereby certify that the foregoing a igned	ent Notice Operations (Clearly state all measured and true vertice (1) Rig up (2) Load ca The BLM will ( st true and correct R. Mah	pertinent details, and give pertine depths for all markers and zond pump truck on casing using with water and be notified 24 hours p	Repair s Casing run integrity test an dates, including estimated date of so pertinent to this work.)* g. pressure test to 500 psi	for 30 mins.
Final Abandonen Describe Proposed or Completed ( give subsurface locations and hereby ceptify that the foregoing a igned	ent Notice Operations (Clearly state all measured and true vertice (1) Rig up (2) Load ca The BLM will ( st true and correct R. Mah	pertinent details, and give pertine depths for all markers and zond pump truck on casing using with water and be notified 24 hours p	Repair s Casing run integrity test at dates, including estimated date of at pertinent to this work.)* g. pressure test to 500 psi prior to testing. e R. Graham	for 30 mins.
Final Abandonan Describe Proposed or Completed ( give subsurface locations and hereby certify that the foregoing a igned	ent Notice Operations (Clearly state all d measured and true vertice (1) Rig up (2) Load ca The BLM will f a true and correct R. Jrah ice use)	pertinent details, and give pertine depths for all methers and zone pump truck on casing using with water and pe notified 24 hours p Candac	Repair s Casing run integrity test an dates, including estimated date of an pertinent to this work.)* g. pressure test to 500 psi prior to testing. e R. Graham ering Tech.	for 30 mins.

•

(Rev. 5/23/94)

## BUREAU OF LAND MANAGEMENT CARLSBAD RESOURCE AREA

## Temporary Abandonment of Wells on Federal Lands

## Conditions of Approval

According to 43 CFR 3162.3-4-c, " No well may be temporarily abandoned for more than 30 days without the prior approval of the authorized officer".

Temporary Abandonment (TA) status approval requires a successful casing integrity test as follows:

- Contact the appropriate BLM office at least 24 hours prior to the scheduled Casing Integrity Test. For wells in Eddy County call (505) 887-6544 ; for wells in Lea County call (505) 393-3612.
- 2. A bridge plug or packer shall be set at a maximum of 50 feet above any open perforations or open hole.
- 3. All downhole production/injection equipment (tubing, rods, etc.) shall be removed from the casing if they are not isolated by a packer.
- 4. The production casing shall be filled with corrosion inhibited fluid and pressure tested to 500 psi. The casing shall be capable of holding this pressure for at least 30 minutes with a 10% allowable leak-off.

Wells that successfully pass the casing integrity test will be approved for Temporary Abandonment (TA) status for 12 months provided that the operator:

1. Submits a subsequent Sundry Notice requesting TA approval,

2. Attaches a clear copy or the original of the pressure test chart,

3. And attaches a detailed justification why the well should not be plugged and abandoned.

The TA status could be extended without another casing integrity test provided there was no leak-off during the test.

If the well does not pass the casing integrity test, then the operator shall within 30 days submit to BLM for approval one of the following:

1. A procedure to repair the casing so that a TA approval can be granted.

2. A procedure to plug and abandon the well.