

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

SUBMIT IN TRIPLICATE*
(Other instruct. on reverse side)

Budget Bureau No. 1004-0135
Expires August 31, 1985

5. LEASE DESIGNATION AND SERIAL NO.
NM05020

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.)

1. OIL WELL ☒ GAS WELL ☐ OTHER ☐		7. UNIT AGREEMENT NAME	
2. NAME OF OPERATOR ARROWHEAD OIL CORPORATION		8. FARM OR LEASE NAME H.E. YATES A FED.	
3. ADDRESS OF OPERATOR BOX 548, ARTESIA, NM 88210		9. WELL NO. 2	
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.* See also space 17 below.) At surface 2260' FNL, 2260' FWL		10. FIELD AND POOL, OR WILDCAT N. HACKBERRY YATES S-R	
14. PERMIT NO.		11. SEC. T., R., N., OR BLK. AND SURVEY OR AREA Sec 29-T19S-R31E	
15. ELEVATIONS (Show whether SP, ST, OR, etc.) 3493' GL		12. COUNTY OR PARISH Eddy	
		13. STATE N.M.	

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF
FRACTURE TREAT
ABANDON OR ACQUIRE
REPAIR WELL
(Other)

☐
☐
☐
☐
☐

RELL OR ALTER CASING
MULTIPLE COMPLETS
ABANDON*
CHANGE PLANS

☐
☐
☒
☐
☐

SUBSEQUENT REPORT OF:

WATER SHUT-OFF
FRACTURE TREATMENT
ABANDON OR ACQUIRE
(Other)

☐
☐
☐
☐
☐

REPAIRING WELL
ALTERING CASING
ABANDONMENT*


☐
☐
☐
☐
☐

(Note: Report results of multiple completion on Well Completion or Resumption Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent data, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all machines and zones pertinent to this work.)

WE PROPOSE TO PLUG & ABANDON AS FOLLOWS:

7" 20# csg is set @ 700' w/50 sax cement; 4½" csg is set @ 2340' w/100 sax cement. We will circulate hole with mud laden fluid; spot a 400' plug @ 2300' back to 1900' and tag. Perf 2 holes @ 750', circulate cement to surface. Install dry hole marker, clean & level location.



18. I hereby certify that the foregoing is true and correct

SIGNED

Shirley Loop

TITLE Production Clerk

DATE 1/21/86

(This space for Federal or State office use)

APPROVED BY

Scott Adams

TITLE

DATE

1-24-86

CONDITIONS OF APPROVAL, IF ANY:

*See Instructions on Reverse Side

