

Submit 3 Copies
to Appropriate
District Office

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION
P.O. Box 2088
Santa Fe, New Mexico 87504-2088

WELL API NO. 30-015-05917
5. Indicate Type of Lease STATE <input type="checkbox"/> FEE <input checked="" type="checkbox"/>
6. State Oil & Gas Lease No.
7. Lease Name or Unit Agreement Name Thomas
8. Well No. 1
9. Pool name or Wildcat Penasco Draw San Andres Yeso
10. Elevation (Show whether DF, RKB, RT, GR, etc.) 3451' GR

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"
(FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well: OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>
2. Name of Operator YATES PETROLEUM CORPORATION
3. Address of Operator 105 South Fourth Street - Artesia, NM 88210

4. Well Location Unit Letter H : 1980 Feet From The North Line and 660 Feet From The East Line Section 8 Township 19S Range 25E NMPM Eddy County
--

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data	
NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>
OTHER: <input type="checkbox"/>	PLUG AND ABANDONMENT <input checked="" type="checkbox"/>
	CASING TEST AND CEMENT JOB <input type="checkbox"/>
	OTHER: <input type="checkbox"/>

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Moved in and rigged up pulling unit. Bled well down. Unflanged wellhead. Rigged up tubing equipment. POOH with tubing. Picked up 5-1/2" tension packer. RIH to 1140' and set. Rigged up pump truck and pumped 44 bbls down tubing. Well went on vacuum. Unset packer and COOH with tubing. Picked up 5-1/2" cement retainer and RIH to 1050'. Set packer. Squeezed 200 sacks cement below retainer. Pulled up retainer. Circulated hole with mud. Spotted 60 sacks cement on top of retainer. POOH with tubing. Spotted 10 sacks cement at surface. Installed regulation abandonment marker. PLUGGED AND ABANDONED - FINAL REPORT. Plugging complete February 28, 1994.

Part ID-2
4-15-94
PFA

I hereby certify that the information above is true and complete to the best of my knowledge and belief.		
SIGNATURE <i>Rusty Klein</i>	TITLE Production Clerk	DATE Mar. 3, 1994
TYPE OR PRINT NAME Rusty Klein		TELEPHONE NO. 505-748-1471

(This space for State Use)

APPROVED BY <i>Michael S. Webb</i>	TITLE Field Rep. I	DATE May 22 94
---------------------------------------	-----------------------	-------------------

CONDITIONS OF APPROVAL, IF ANY: