

STATE OF NEW MEXICO
ENERGY AND MINERALS DEPARTMENT

OIL CONSERVATION DIVISION

Form C-103
Revised 10-1-70

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	<input checked="" type="checkbox"/>
FILE	<input checked="" type="checkbox"/>
U.S.G.S.	
LAND OFFICE	
OPERATOR	<input checked="" type="checkbox"/>

RECEIVED BY
SANTA FE, NEW MEXICO 87501

AUG 30 1985

O. C. D.

5a. Indicate Type of Lease	
State <input checked="" type="checkbox"/>	Fee <input type="checkbox"/>
5. State Oil & Gas Lease No. E-7345	

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.
USE "APPLICATION FOR PERMIT - I" (FORM C-101) FOR SUCH PROPOSALS.)

1. <input checked="" type="checkbox"/> OIL WELL <input type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER		7. Unit Agreement Name
2. Name of Operator ARROWHEAD OIL CORPORATION		8. Farm or Lease Name MACHRIS STATE
3. Address of Operator P.O. Box 548, ARTESIA, NEW MEXICO 88210		9. Well No. 1
4. Location of well UNIT LETTER <u>A</u> <u>330</u> FEET FROM THE <u>NORTH</u> LINE AND <u>970</u> FEET FROM <u>EAST</u> <u>32</u> <u>19-South</u> <u>31-East</u> THE _____ LINE, SECTION _____ TOWNSHIP _____ RANGE _____ NMPM.		10. Field and Pool, or Wildcat Hackberry Yates SR-Nor
15. Elevation (Show whether DF, RT, GR, etc.) 3483' RT		12. County EDDY

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input checked="" type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOB <input type="checkbox"/>	

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

We propose to plug & abandon by setting a 50' plug through the open hole @ 2263'-2213'. Tag plug, run freepoint, estimate freepoint & shoot csg. off. Estimated cut off @ 1900'.
Set 50' plug in & out of stub. Tag cement plug, set 1100' plug through salt section.
Set 50' plug in & out of 7", set 15' plug @ surface.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED Shirley Loop TITLE Production Clerk DATE 8/21/85

APPROVED BY Mike Williams TITLE OIL AND GAS INSPECTOR DATE SEP 04 1985

CONDITIONS OF APPROVAL, IF ANY: