

NMOCC COPY

DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT" for such proposals.)

1. ☒ OIL WELL ☒ GAS WELL ☐ OTHER

2. NAME OF OPERATOR Tenneco Oil Company

3. ADDRESS OF OPERATOR 1860 Lincoln St., Suite 1200, Denver, Colo. 80295

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.
See also space 17 below.)
At surface

RECEIVED

OCT 19 1977

14. PERMIT NO.

15. ELEVATIONS (Show whether DE, RT, OR GL) D. C. C.
3540' GL ARTESIA, OFFICE

5. LEASE DESIGNATION AND SERIAL NO.
NM-0107697

6. IF INDIAN, ALLOTTEE OR TRUST NAME
copy to SF

7. UNIT AGREEMENT NAME

8. FARM OR LEASE NAME
Jones Federal

9. WELL NO.
1

10. FIELD AND POOL, OR WILDCAT
Lusk Strawn

11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA
Sec. 24, T19S, R31E

12. COUNTY OR PARISH
Eddy

13. STATE
New Mexico

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF ☐
FRACTURE TREAT ☐
SHOOT OR ACIDIZE ☒
REPAIR WELL ☐
(Other) ☐

PULL OR ALTER CASING ☐
MULTIPLE COMPLETE ☐
ABANDON* ☐
CHANGE PLANS ☐

SUBSEQUENT REPORT OF:

WATER SHUT-OFF ☐
FRACTURE TREATMENT ☐
SHOOTING OR ACIDIZING ☐
(Other) ☐

REPAIRING WELL ☐
ALTERING CASING ☐
ABANDONMENT* ☒

(NOTE: Report results of multiple completion on Well
• Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)

We propose to reperforate and restimulate this well as follows:

MIRUPU and pull tubing. Run Gamma Ray Correlation log. Perforate 2 JSPF from 11414' - 37', 11461' - 69' and 11474' - 81'. Set packer at 11300'. Test for leaks. Stimulate as necessary to establish commercial production. Pull packer. Swab well. Run production equipment and place well back on production. Clean location of all debris and fill and level all pits.

RECEIVED

OCT 17 1977

U. S. GEOLOGICAL SURVEY
ARTESIA, NEW MEXICO

18. I hereby certify that the foregoing is true and correct

SIGNED [Signature]

TITLE Div. Production Manager

DATE 10/17/77

(This space for Federal or State office use)

APPROVED BY [Signature]
CONDITIONS OF APPROVAL, IF ANY:

TITLE ACTING DISTRICT ENGINEER

DATE OCT 18 1977

*See Instructions on Reverse Side