

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEYSUBMIT IN TRIPLICATE*
(Other instructions on re-
verse side)Form approved.
Budget Bureau No. 42-R1424.

5. LEASE DESIGNATION AND SERIAL NO.

New Mexico 04097

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

7. UNIT AGREEMENT NAME

8. FARM OR LEASE NAME

Federal "NY"

9. WELL NO.

1-20

10. FIELD AND POOL, OR WILDCAT

North Hackberry (Tates)

11. SEC., T., R., M., OR BLM. AND
SURVEY OR AREA

Sec. 20, T19S., R31E.

12. COUNTY OR PARISH

Eddy

13. STATE

New Mexico

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.)

1.

OIL WELL ☐ GAS WELL ☐ OTHER ☒

DRY HOLE

2. NAME OF OPERATOR

John H. Trigg

3. ADDRESS OF OPERATOR

P. O. Box 520, Roswell, New Mexico, 88201

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.*
See also space 17 below.)

At surface

2210' From North Line & 2310' From East Line

14. PERMIT NO.

15. ELEVATIONS (Show whether DF, RT, GR, etc.)

3423.5 Gr.

3425.5 DF

16.

Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF

PULL OR ALTER CASING

FRACTURE TREAT

MULTIPLE COMPLETE

SHOOT OR ACIDIZE

ABANDON*

REPAIR WELL

CHANGE PLANS

(Other)

SUBSEQUENT REPORT OF:

WATER SHUT-OFF

REPAIRING WELL

FRACTURE TREATMENT

ALTERING CASING

SHOOTING OR ACIDIZING

ABANDONMENT*

(Other)

(NOTE: Report results of multiple completion on Well
Completion or Recompletion Report and Log form.)17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any
proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones perti-
nent to this work.)*

May 7, 1964

Drilled to T. D. 2206' at 1:30 P. M. Pulled 14 joints (432 feet)
of 8 5/8 inch, 24# casing.

May 8, 1964

Plugged well per verbal instructions and approval received from
U. S. G. S. on 5/7/64 as follows:

Set 35 sack cement plug from 2000 - 2100 feet

Set 35 sack cement plug from 550 - 650 feet

Set 10 sack cement plug at the surface

Job completed at 11:00 a.m. 5/8/64.

Surface marker has not been erected. Notice will be given when
this has been accomplished and location is ready for inspection.

RECEIVED

AUG 13 1964

O. C. C.
ARTESIA OFFICE

18. I hereby certify that the foregoing is true and correct

ORIGINAL SIGNED BY

SIGNED

Gerald E. Harrington

TITLE

Geologist

DATE

May 8, 1964

(This space for Federal or State office use)

APPROVED BY

SIGNATURE OF APPROVAL, IF ANY:

TITLE

DATE

H. L. BEECHAM
ACTING DISTRICT ENGINEER

*See Instructions on Reverse Side

Instructions

General: This form is designed for submitting proposals to perform certain well operations, and reports of such operations when completed, as indicated, on Federal and Indian lands pursuant to applicable Federal law and regulations, and, if approved or accepted by any State, on all lands in such State, pursuant to applicable State law and regulations. Any necessary special instructions concerning the use of this form and the number of copies to be submitted, particularly with regard to local, area, or regional procedures and practices, either are shown below or will be issued by, or may be obtained from, the local Federal and/or State office.

Item 4: If there are no applicable State requirements, locations on Federal or Indian land should be described in accordance with Federal requirements. Consult local State or Federal office for specific instructions.

Item 17: Proposals to abandon a well and subsequent reports of abandonment should include such special information as is required by local Federal and/or State offices. In addition, such proposals and reports should include reasons for the abandonment; data on any former or present productive zones, or other zones with present significant fluid contents not sealed off by cement or otherwise; depths (top and bottom) and method of placement of cement plugs; mud or other material placed below, between and above plugs; amount, size, method of parting of any casing, liner or tubing pulled and the depth to top of any left in the hole; method of closing top of well; and date well site conditioned for final inspection looking to approval of the abandonment.