

UNITED STATES  
DEPARTMENT OF THE INTERIOR  
GEOLOGICAL SURVEY

Artesia, NM 88210

SUBMIT IN TRIPLICATE\*  
(Other instructions on re-  
verse side)

Form approved.  
Budget Bureau No. 42-21424.

5. LEASE DESIGNATION AND SERIAL NO.

LC-029387 (d)

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

7. UNIT AGREEMENT NAME

8. FARM OR LEASE NAME

Kenwood Federal

9. WELL NO.

4

10. FIELD AND POOL, OR WILDCAT

Shugart (Y,SR,Q,G)

11. SEC., T., S., M., OR BLE. AND  
SURVEY OR AREA

Sec. 19, T-18-S, R-31-E

12. COUNTY OR PARISH 13. STATE

Eddy

N.M.

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back any well or to alter or  
Use "APPLICATION FOR PERMIT—" for such proposals.)

1. OIL WELL ☒ GAS WELL ☐ OTHER ☐

2. NAME OF OPERATOR

Southland Royalty Company

3. ADDRESS OF OPERATOR

21 Desta Drive, Midland, Texas 79705

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.\*  
See also space 17 below.)  
At surface

830' FWL & 1650' FSL, Sec. 19, T-18-S, R-31-E

14. PERMIT NO.

15. ELEVATIONS (Show whether DF, RT, GR, etc.)

3628' GR

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF

PULL OR ALTER CASING

FRACTURE TREAT

MULTIPLE COMPLETE

SHOOT OR ACIDIZE

ABANDON\*

REPAIR WELL

CHANGE PLANS

(Other)

SUBSEQUENT REPORT OF:

WATER SHUT-OFF

REPAIRING WELL

FRACTURE TREATMENT

ALTERING CASING

SHOOTING OR ACIDIZING

ABANDONMENT\*

(Other)

(NOTE: Report results of multiple completion on Well  
Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any  
proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones perti-  
nent to this work.)\*

MIRU. RIH w/4 3/4" bit, 3 1/2" DC's & 2 7/8" tbg. Tag @ 1541'. Reverse drlg to 1560'.  
Fell out to 3222'. Circ hole clean. Pull to 3160'. Spotted 50 sx C1 "C" Neat. POH.  
RIH w/tbg. Tag plug @ 3005'. Circ hole w/10# brine mud. Pull to 1921' & spot 50 sx  
C1 "C" cmt. POH. Tag plug @ 1820'. Circ hole. Pull to 806'. Spot 30 sxs C1 "C".  
POH. WOC 4 hrs. RIH w/tbg. Didn't tag plug. Spot 100 sxs C1 "C" @ 806'. POH. WOC 4  
hrs. RIH & tag plug @ 500'. Pull to 60' & circ cmt to surf. POH. Rlrd rig. Weld on  
dry hole marker & clean location. Well plugged & abandoned 4/5/84.

Cathy Nokes  
Dennis Sledge  
G. Slaughter  
J. Hyatt  
Well File  
B. Noland  
Bill Dawson  
Donny Davis  
Sandy Houston  
Gayle Anderwald  
RRC  
Date \_\_\_\_\_

18. I hereby certify that the foregoing is true and correct

SIGNED

*John Stark*

TITLE

Operations Engineer

DATE

4/10/84

(This space for Federal or State office use)  
Orig. Sgd. Charles S. Egan

APPROVED BY

Area Manager

TITLE

DATE

2-28-85  
APR 11 1984

CONDITIONS OF APPROVAL, IF ANY: