

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEYSUBMIT IN TRIPL. TP*
(Other instructions on re-
verse side)Form approved.
Budget Bureau No. 42-R1424.

5. LEASE DESIGNATION AND SERIAL NO.

LC 063696

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

Copy to 27.

7. UNIT AGREEMENT NAME

8. FARM OR LEASE NAME

Barton "B" Federal

9. WELL NO.

10. FIELD AND POOL, OR WILDCAT

Undesignated *Strawn*11. SEC., T., R., M., OR BLK. AND
SURVEY OR AREA

Sec. 22, T-19-S, R-31-E

12. COUNTY OR PARISH

Eddy

13. STATE

New Mexico

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.)

1.

OIL ☒ GAS ☐
WELL WELL OTHER

2. NAME OF OPERATOR

Tenneco Oil Company

3. ADDRESS OF OPERATOR

Box 1031, Midland, Texas

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.*
See also space 17 below.)
At surface

1980' FNL & 660' FEL of Section 22

14. PERMIT NO.

15. ELEVATIONS (Show depth - FE, M, GR, etc.)

3534 GL

16.

Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF ☐FRACTURE TREAT ☐SHOOT OR ACIDIZE ☐REPAIR WELL ☐

(Other)

PULL OR ALTER CASING ☐MULTIPLE COMPLETE ☐ABANDON* ☒CHANGE PLANS ☐

SUBSEQUENT REPORT OF:

WATER SHUT-OFF ☐FRACTURE TREATMENT ☐SHOOTING OR ACIDIZING ☐

(Other)

REPAIRING WELL ☐ALTERING CASING ☐ABANDONMENT* ☐(NOTE: Report results of multiple completion on Well
Completion or Recompletion Report and Log form.)17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any
proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones perti-
nent to this work.)*

Plans are to plug well as follows:

Set 80 sx cmt plug 11100-11385 across Strawn Reef
Set 30 sx cmt plug 10525-10625 Top of Cisco Shale.
Set 30 sx cmt plug 8900-9000 Top of Second Bone Springs
Set 30 sx cmt plug 6875-6975 Top of Bone Springs Lime
Set 30 sx cmt plug 4350-4450 Top of Delaware Sd
Set 30 sx cmt plug 3940 - 4040 Bottom of 8-5/8" csg.
Set 30 sx cmt plug 1900-2000 top of 8-5/8" csg.
Set 30 sx cmt plug 620-720 bottom of 13-3/8" csg.
Set 10 sx cmt plug at surface - 20 and install dry hole marker.
Approximately 2042' - 8-5/8" csg and all 13-3/8" csg. to be left in hole.
Verbal approval of above program by Mr. Chuck to Frank Collins 6-3-65.

RECEIVED

JUN 18 1965

U. S. GEOLOGICAL SURVEY
ARTESIA, NEW MEXICORECEIVED
JUN 10 1965
U. S. GEOLOGICAL SURVEY
ARTESIA, NEW MEXICO

18. I hereby certify that the foregoing is true and correct

SIGNED *A. W. Lang* A. W. Lang TITLE *Asst. Dir. Superintendent* DATE *6-8-65*

(This space for Federal or State office use)

APPROVED BY
CONDITIONS OF APPROVAL, IF ANY:

TITLE

DATE

APPROVED
JUN 11 1965
H. L. BLOOM
ACTING DISTRICT ENGINEER

*See Instructions on Reverse Side