	• N. M.	O. C. C. COPY				
Form 9-331 (May 1963)	LivITED STAT DEPARTMENT OF THE	ES	Other instructives	E* Form approv Budget Bure 5. LEASE DESIGNATION	au No. 42-R1424.	
	GEOLOGICAL SU		Copy 4	1 NM 015085		
CLIND	DV NOTICES AND DE	DODIE ON	WELLS	6. IF INDIAN, ALLOTTE	E OR TRIBE NAME	
	RY NOTICES AND RE	non on plug hook t	WELLS			
(Do not use this ke	Use "APPLICATION FOR PERMIT-	-" for such proper	EBEIVE	- 이유한 물		
				7. UNIT AGREEMENT N.	ME	
OIL GAS WELL WELL OTHER						
NAME OF OPERATOR			AV BE CONTRACTOR	8. FARM OR LEASE NAM	ME	
Mobil Oil Corp ADDRESS OF OPERATOR	poration	·	<u>proj</u> <u>proj</u>	Federal "W" 9. WELL NO.		
		01	ARTESIA, DITICE		가 나는 가 주. - 한 국 방 수 있는 것	
P. O. BOX 033	Midland, Texas 7970 port location clearly and in accordan	OL nce with any State	e requirements.*	10. FIELD AND POOL, O	R WILDCAT	
See also space 17 below At surface	.)		Undesignated			
		0 0 0 25 5	Eddy County	11. SEC., T., R., M., OR	BLK. AND	
-	30' FEL, Sec. 30, T-20	0-5, K-2J-1	, Eady Councy,	SURVEY OR AREA		
New Mexico				Sec. 30, T-2	20-S, R-25-	
4. PERMIT NO.	15. ELEVATIONS (She	ow whether DF, RT, a	GR, etc.)	12. COUNTY OR PARISH	1 13. STATE	
	1	3553 GL		Eddy	New Mexi	
6.	Check Appropriate Box To	Indicate Natur	e of Notice Report of	Other Data		
		indicate 14010		ానిసి ఇంది ఈ		
NO	TICE OF INTENTION TO:		SUBS	EQUENT REPORT OF:	5 - - - - -	
TEST WATER SHUT-OFF	PULL OR ALTER CASING	c	WATER SHUT-OFF	REPAIRING	WELL	
FRACTURE TREAT	MULTIPLE COMPLETE	X	FRACTURE TREATMENT	ALTERING C		
SHOOT OR ACIDIZE	ABANDON*	^	SHOOTING OR ACIDIZING	ABANDONME	NT*	
REPAIR WELL	CHANGE PLANS		(Other) (Note: Report resu	ilts of multiple completion	on Well	
(Other)	COMPLETED OPERATIONS (Clearly stat	e all nertinent det		mpletion Report and Log fo tes, including estimated da		
from 9443 to shut down for to pick 4½" c down 7000' of laying down t and pull 4½" cut 4½" Casin 4%" casing. P	d pkr, re-ran tubing 9271. Job complete a nite. Finished pull asing up off slips in 2-3/8 tubing with ca bg, moved out X-Pert casing. Rig up Dia-L g @ 6810. Unable to repare to run 2-3/8"	t 3:00 p.m. ing tbg. ri hangar. H tline, prep Well Servic Log, ran log Pull Jet, o tbg. and sp	. 6-4-66. Pulled igged up Dia-Log Pulled 80,000# De to change out ce, MIRU DA & S I g from 3000-7400, cut @ 6530. Pull pot plugs. Ran 2	l 250 joints tub w/4½" Spear. A errick Buckled. pulling units. DD Unit. Prep. , check the pipe led and laid down 2-3/8" tbg. OE to	ing and ttempted Laid Finished to cut Jet n 204 joint o 6508,	
Howco spotted	35 sx Regular Neat C	ement from	6580-6432, then			
then spotted	60 sx, 2885-2707, rem	loved casing	s neau, sporreu (
Iace, Install	State Marker.			REAL PROPERTY OF		
	•		:		6	
			•	READER A	SURVIO	
			•		ALATXIN	
	· /)			FOL N	EN	
	• / /			S-JECTA		
				U. ARTES		
18. I hereby certify that t	he foregoing is true and correct					
8IGNED	I. A. Payne	TITLE Aut	horized Agent	DATE <u>8-1</u>	<u>0-66</u>	
(This space for Feder				1997 A.		
	PROVAL, IF ANY:	TITLE	·······	DATE		
	ô I					
AUG 12	mari					
HEEKINA	NINIFER *Soo	Instructions on	Reverse Side		and the set	
H. L. BEEKINA ACTING DISTRICT EN						
ACTING						

ķ

.1