

NO. OF COPIES RECEIVED	6
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

SUNDRY NOTICES AND REPORTS ON WELLS <small>(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)</small>		5a. Indicate Type of Lease State <input checked="" type="checkbox"/> Fee <input type="checkbox"/>
		5. State Oil & Gas Lease No. OG-272
1. OIL WELL <input type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER- DRY HOLE	7. Unit Agreement Name	
2. Name of Operator SOUTHWEST PRODUCTION CORPORATION	8. Farm or Lease Name LOWE STATE	
3. Address of Operator <i>P.O. Box 1464, Midland, Texas</i> P. O. Box 936, Roswell, New Mexico 88201	9. Well No. 1	
4. Location of Well UNIT LETTER G 1980 FEET FROM THE North LINE AND 1980 FEET FROM THE East LINE, SECTION 11 TOWNSHIP 19S RANGE 28E NMPM.	10. Field and Pool, or Wildcat E. Millman-Qn., Gbg.	
15. Elevation (Show whether DF, RT, GR, etc.) GR 3435		12. County EDDY

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data			
NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input checked="" type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOBS <input type="checkbox"/>	OTHER <input type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

**4½ Casing shot off at approximately 1400' and pulled.
Cement plugs set as follows with mud between plugs:**

**60 sacks @ 2294-1750 (Top perf @ 1803)
100' plug at stub of 4½" casing.
100' Plug at base of surface casing 575-675
10 sack plug at surface.**

Dryhole marker installed, pits filled, location leveled and cleaned.

RECEIVED

FEB 14 1969

O. C. C.
ARTERIA, OFFICE

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED H. Lee Harvard TITLE Manager DATE 2/13/69

APPROVED BY R. J. Starnes TITLE OIL AND GAS INSPECTOR DATE DEC 10 1969

CONDITIONS OF APPROVAL, IF ANY: