NO. OF COPIES RECEIV	ED 7			Form C-103
DISTRIBUTION				Supersedes Old
SANTA FE	7	NEW MEXICO OIL CON	ISERVATION COMMISSION	C-102 and C-103 Effective 1-1-65
FILE	1-			
U.S.G.S.				5a. Indicate Type of Lease
LAND OFFICE				State X Fee.
OPERATOR	15			5. State Oil & Gas Lease No.
				OG 272
(DO NOT USE TH	SUNDRY NO	TICES AND REPORTS OF TO DRILL OR TO DEEPEN OR PLUG	BACK TO A DIFFERENT RESERVOIS	
OIL TY	GAS OT	THER- /		7. Unit Agreement Name N/A
2. Name of Operator				8, Farm or Lease Name
	st Producti	on Corporation		Lowe State
3. Address of Operator P.O. Bo	x 13497 N.T	. Station, Dento	n, Texas	9. Well No. 2
4. Location of Well				10.[Field and Peo], of Misson
UNIT LETTER	"H" 1980	FEET FROM THENOT	th LINE AND 990	FEET FROM Millman, Q-Gybg.
74		ר ר -	9 s 28E	
THE LEST	LINE, SECTION	11 TOWNSHIP 19	98 RANGE 28E	NMPM. (())
mmmm	mmm	15. Elevation (Show whethe	r DF, RT, GR, etc.)	12, County
		(3430	Eddy
16.	Charle Appea		· · · · · · · · · · · · · · · · · · ·	
N	Check Appro	opriate Box To Indicate : TION TO:	-	REPORT OF:
• • • • • • • • • • • • • • • • • • • •				
PERFORM REMEDIAL WOR	ĸ 🔲	PLUG AND ABANDON	REMEDIAL WORK	ALTERING CASING
	* 🔲	PLUG AND ABANDON	REMEDIAL WORK COMMENCE DRILLING OPNS.	ALTERING CASING PLUG AND ABANDONMENT
PERFORM REMEDIAL WOR	K []	PLUG AND ABANDON CHANGE PLANS	COMMENCE DRILLING OPNS. CASING TEST AND CEMENT JOE	PLUG AND ABANDONMENT
PERFORM REMEDIAL WOR	K		COMMENCE DRILLING OPNS.	PLUG AND ABANDONMENT
PERFORM REMEDIAL WOR	* []		COMMENCE DRILLING OPNS. CASING TEST AND CEMENT JOE	PLUG AND ABANDONMENT
PERFORM REMEDIAL WORTEMPORARILY ABANDON PULL OR ALTER CASING OTHER 17. Describe Proposed (work) SEE RULE 1	or Completed Operation	CHANGE PLANS DE (Clearly state all pertinent de	commence drilling opns. casing test and cement jos other Perf. tails, and give pertinent dates,	PLUG AND ABANDONMENT And Stimulation. X
PERFORM REMEDIAL WOR TEMPORARILY ABANDON PULL OR ALTER CASING OTHER 17. Describe Proposed (work) SEE RULE 1 11-17-66	or Completed Operation fos. TD 2254.	change plans Clearly state all persinent de Logged hole. Ra:	commence drilling opns. casing test and cement joe Perf. other Perf. tails, and give pertinent dates,	PLUG AND ABANDONMENT And Stimulation.
PERFORM REMEDIAL WORTEMPORARILY ABANDON PULL OR ALTER CASING OTHER 17. Describe Proposed (work) SEE RULE 1 11-17-66	TD 2254. sx. cement Held OK. Perforated 2040. 2049	Logged hole. Rate of PD 5:30 PM.	commence drilling opns. casing test and cement jor Perf. tails, and give pertinent dates, n 2240 4½ , 9½ WOC 18 hours.) at 1840, 1845, 68, 2070, 2094,	including estimated date of starting any proposed, set at 2235! w/ 75 Tested w/ 1000# 1 hr. 1850, 1953, 1975, 2099, 2104, 2108,
PERFORM REMEDIAL WORTEMPORARILY ABANDON PULL OR ALTER CASING OTHER 17. Describe Proposed (work) SEE RULE 1 11-17-66	TD 2254. sx. cement Held OK. Perforated 2040, 2049 2123, 2141 Treated wi	CHANGE PLANS DIS (Clearly state all persinent de Logged hole. Rat. PD 5:30 PM. 1 Shot/ft. 2052, 2061, 206, 2144, 2148, 216	commence Drilling opns. casing test and cement joe Perf. tails, and give pertinent dates, n 2240 4½ , 9½ / 100 /	including estimated date of starting any proposed, set at 2235! w/ 75 Tested w/ 1000# 1 hr. 1850, 1953, 1975, 2099, 2104, 2108,
PERFORM REMEDIAL WORTEMPORARILY ABANDON PULL OR ALTER CASING OTHER 17. Describe Proposed (work) SEE RULE 1 11-17-66	TD 2254. sx. cement Held OK. Perforated 2040, 2049 2123, 2141 Treated wi	CHANGE PLANS THE Color of the	commence drilling opns. casing test and cement jor Perf. tails, and give pertinent dates, n 2240 4½ , 9½ WOC 18 hours.) at 1840, 1845, 68, 2070, 2094, 63, 2166, 2175, d. Fraced with nd.	including estimated date of starting any proposed, set at 2235 w/ 75 Tested w/ 1000# 1 hr. 1850, 1953, 1975, 2099, 2104, 2108, 2176.
PERFORM REMEDIAL WORTEMPORARILY ABANDON PULL OR ALTER CASING OTHER 17. Describe Proposed of work) SEE RULE'1 11-17-66 11-25-66	TD 2254. sx. cement Held OK. Perforated 2040, 2049 2123, 2141 Treated wi water and	CHANGE PLANS DIAS (Clearly state all pertinent de Logged hole. Rat. PD 5:30 PM. (1/5", 1 shot/ft., 2052, 2061, 206, 2144, 2148, 216 th 500 gals. acid 60,000# 20-40 sat	commence drilling opns. casing test and cement jor Perf. tails, and give pertinent dates, n 2240 4½ , 9½ WOC 18 hours.) at 1840, 1845, 68, 2070, 2094, 63, 2166, 2175, d. Fraced with nd.	including estimated date of starting any proposed, set at 2235! w/ 75 Tested w/ 1000# 1 hr. 1850, 1953, 1975, 2099, 2104, 2108, 2176. 36,000 gals. jelled
PERFORM REMEDIAL WORTEMPORARILY ABANDON PULL OR ALTER CASING OTHER 17. Describe Proposed of work) SEE RULE'1 11-17-66 11-25-66	TD 2254. sx. cement Held OK. Perforated 2040, 2049 2123, 2141 Treated wi	CHANGE PLANS DIAS (Clearly state all pertinent de Logged hole. Rat. PD 5:30 PM. (1/5", 1 shot/ft., 2052, 2061, 206, 2144, 2148, 216 th 500 gals. acid 60,000# 20-40 sat	commence drilling opns. casing test and cement jor Perf. tails, and give pertinent dates, n 2240 4½ , 9½ WOC 18 hours.) at 1840, 1845, 68, 2070, 2094, 63, 2166, 2175, d. Fraced with nd.	including estimated date of starting any proposed, set at 2235' w/ 75 Tested w/ 1000# 1 hr. 1850, 1953, 1975, 2099, 2104, 2108, 2176. 36,000 gals. jelled ECEIVED DEC 1 5 1956
PERFORM REMEDIAL WORTEMPORARILY ABANDON PULL OR ALTER CASING OTHER 17. Describe Proposed of work) SEE RULE'1 11-17-66 11-25-66	TD 2254. sx. cement Held OK. Perforated 2040, 2049 2123, 2141 Treated wi water and	CHANGE PLANS DIAS (Clearly state all pertinent de Logged hole. Rat. PD 5:30 PM. (1/5", 1 shot/ft., 2052, 2061, 206, 2144, 2148, 216 th 500 gals. acid 60,000# 20-40 sat	commence drilling opns. casing test and cement jor Perf. tails, and give pertinent dates, n 2240 4½ , 9½ WOC 18 hours.) at 1840, 1845, 68, 2070, 2094, 63, 2166, 2175, d. Fraced with nd.	including estimated date of starting any proposed, set at 2235 w/ 75 Tested w/ 1000# 1 hr. 1850, 1953, 1975, 2099, 2104, 2108, 2176. 36,000 gals. jelled ECEIVED
PERFORM REMEDIAL WORTEMPORARILY ABANDON PULL OR ALTER CASING OTHER 17. Describe Proposed of work) SEE RULE'1 11-17-66 11-25-66	TD 2254. sx. cement Held OK. Perforated 2040, 2049 2123, 2141 Treated wi water and	CHANGE PLANS DIAS (Clearly state all pertinent de Logged hole. Rat. PD 5:30 PM. (1/5", 1 shot/ft., 2052, 2061, 206, 2144, 2148, 216 th 500 gals. acid 60,000# 20-40 sat	commence drilling opns. casing test and cement jor Perf. tails, and give pertinent dates, n 2240 4½ , 9½ WOC 18 hours.) at 1840, 1845, 68, 2070, 2094, 63, 2166, 2175, d. Fraced with nd.	including estimated date of starting any proposed, set at 2235 w/ 75 Tested w/ 1000# 1 hr. 1850, 1953, 1975, 2099, 2104, 2108, 2176. 36,000 gals. jelled ECEIVED DEC 1 & 1956

OIL AND GAS INSPECTOR

12-12-66

DEC 1 4 1966

CONDITIONS OF APPROVAL, IF ANY