

C/SF
AP

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION
P.O. Box 2088
Santa Fe, New Mexico 87504-2088

WELL API NO.	30-015-20069
5. Indicate Type of Lease	STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
6. State Oil & Gas Lease No.	V-4567
7. Lease Name or Unit Agreement Name	Rudolph ATX State
8. Well No.	1
9. Pool name or Wildcat	Lusk Morrow, West

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE APPLICATION FOR PERMIT (FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well: OIL WELL <input type="checkbox"/> GAS WELL <input checked="" type="checkbox"/> OTHER <input type="checkbox"/>	2. Name of Operator YATES PETROLEUM CORPORATION
3. Address of Operator 105 South 4th St., Artesia, NM 88210	4. Well Location Unit Letter <u>A</u> : <u>660</u> Feet From The <u>North</u> Line and <u>660</u> Feet From The <u>East</u> Line Section <u>16</u> Township <u>19S</u> Range <u>31E</u> NMPM <u>Eddy</u> County
10. Elevation (Show whether DF, RKB, RT, GR, etc.) 3534.9' GR	

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER: <input type="checkbox"/>	CASING TEST AND CEMENT JOB <input type="checkbox"/>	OTHER: Perforate, acidize & frac <input checked="" type="checkbox"/>

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

5-3-2000 - Moved in and rigged up pulling unit. Nippled up 5K frac valve and BOP. Rigged up wireline. TIH with logging tools and ran CBL/GR/CCL log. TOOH with logging tools and rigged down wireline. TIH with bit, scraper and 2-3/8" tubing.

5-4-2000 - Pickled tubing and casing with 750 gallons of 15% iron control HCL acid. TOOH with bit, scraper & tubing. Rigged up wireline. TIH with 3-3/8" casing guns and perforated 12335-12366' w/42 .42" holes as follows: 12335-12338' and 12364-12366' (6 SPF - Morrow). TOOH with casing guns and rigged down wireline. TIH with RBP, packer and tubing.

5-5-2000 - Straddled perforations 12364-12366' and acidized with 500 gallons of 7-1/2% Morrow acid. Perforations communicated. Moved tools and straddled all perforations. NOTE: Packer set at 12273' and tested to 1000 psi. Started acidizing and packer gave up. Released packer & reversed out acid. TOOH with packer, RBP and tubing. TIH with 10K packer with on/off tool (1.81"). Set packer at 12273' and tested to 1000 psi. Get off packer. Acidized with 1000 gallons 7-1/2% Morrow acid. Swabbed.. Shut well in.

5-6-8-2000 - Swabbed & flow tested. Shut well in.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Rusty Klein TITLE Operations Technician DATE June 12, 2000

TYPE OR PRINT NAME Rusty Klein TELEPHONE NO. 505/748-1471

(This space for State Use)

ORIGINAL SIGNED BY TIM W. GUM
DISTRICT II SUPERVISOR

JUN 15 2000

APPROVED BY _____ TITLE _____ DATE _____

CONDITIONS OF APPROVAL, IF ANY: