

45F

Form 9-331  
Dec. 1979  
RECEIVED BY  
JAN 22 1985  
O.C.D.  
ARTESIA OFFICE

UNITED STATES  
DEPARTMENT OF THE INTERIOR  
GEOLOGICAL SURVEY

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use Form 9-331-C for such proposals.)

Form Approved.  
Budget Bureau No. 42-R1424

1. oil ☒ well gas ☐ well other ☐
2. NAME OF OPERATOR  
Harvey E. Yates Company ✓
3. ADDRESS OF OPERATOR  
P. O. Box 1933, Roswell, NM 88201
4. LOCATION OF WELL (REPORT LOCATION CLEARLY. See space 17 below.)  
AT SURFACE: 660' FNL & 1980' FEL  
AT TOP PROD. INTERVAL:  
AT TOTAL DEPTH: Same
16. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

REQUEST FOR APPROVAL TO:	SUBSEQUENT REPORT OF:
TEST WATER SHUT-OFF <input type="checkbox"/>	<input type="checkbox"/>
FRACTURE TREAT <input type="checkbox"/>	<input type="checkbox"/>
SHOOT OR ACIDIZE <input type="checkbox"/>	<input type="checkbox"/>
REPAIR WELL <input type="checkbox"/>	<input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	<input type="checkbox"/>
MULTIPLE COMPLETE <input type="checkbox"/>	<input type="checkbox"/>
CHANGE ZONES <input type="checkbox"/>	<input type="checkbox"/>
ABANDON* <input checked="" type="checkbox"/>	<input type="checkbox"/>
(other) <input type="checkbox"/>	<input type="checkbox"/>

5. LEASE  
EC-062052
6. IF INDIAN, ALLOTTEE OR TRIBE NAME
7. UNIT AGREEMENT NAME
8. FARM OR LEASE NAME  
Hudson Federal
9. WELL NO.  
1
10. FIELD OR WILDCAT NAME  
Wildcat - Bone Spring
11. SEC T., R., M., OR BKK. AND SURVEY OR AREA  
Sec. 11, T-18S, R-31E
12. COUNTY OR PARISH 13. STATE  
Eddy NM
14. API NO.
15. ELEVATIONS (SHOW DF, KDB, AND WD)  
3757' GL


(NOTE: Report results of multiple completion or zone change on Form 9-330.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)\*

PROCEDURE FOR P & A:

1. Set 200' plug from 2110' to 1910' & Tag.
2. Set 100' plug over 13 3/8" shoe from 850' to 700'.
3. Set 50' surface plug.

Verbal approval per Bob Pitsche 12/13/84



Subsurface Safety Valve: Manu. and Type \_\_\_\_\_ Set @ \_\_\_\_\_ Ft.

18. I hereby certify that the foregoing is true and correct

SIGNED Ray A. [Signature] TITLE Reservoir Eng. DATE 12/13/84

(This space for Federal or State office use)

APPROVED BY \_\_\_\_\_ TITLE 1-21-85 DATE \_\_\_\_\_  
CONDITIONS OF APPROVAL, IF ANY: