

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

SUBMIT IN TRIPLICATE*
(Other instructions on reverse side)

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use "APPLICATION FOR PERMIT—" for such proposals.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>		RECEIVED		5. LEASE DESIGNATION NM-014103
2. NAME OF OPERATOR Gulf Oil Corporation		DEC 8 1972		6. IF INDIAN, ALLOTTEE OR TRIBE NAME
3. ADDRESS OF OPERATOR Box 670, Hobbs, New Mexico 88240		ARTESIA, OFFICE		7. UNIT AGREEMENT NAME
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements. See also space 17 below.) At surface 660' FNL & 1980' FEL, Section 22, 18-S, 31-E		10. FIELD AND POOL, OR WILDCAT 10		8. FARM OR LEASE NAME Littlefield "AB" Federal
14. PERMIT NO.		15. ELEVATIONS (Show whether DF, RT, GR, etc.) 3661' GL		9. WELL NO. 10
				11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA Sec 22 18-S 31-E
				12. COUNTY OR PARISH Eddy
				13. STATE New Mexico

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
TEST WATER SHUT-OFF <input type="checkbox"/>	PULL OR ALTER CASING <input type="checkbox"/>	WATER SHUT-OFF <input type="checkbox"/>	REPAIRING WELL <input type="checkbox"/>
FRACTURE TREAT <input type="checkbox"/>	MULTIPLE COMPLETE <input type="checkbox"/>	FRACTURE TREATMENT <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
SHOOT OR ACIDIZE <input type="checkbox"/>	ABANDON* <input type="checkbox"/>	SHOOTING OR ACIDIZING <input type="checkbox"/>	ABANDONMENT* <input type="checkbox"/>
REPAIR WELL <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	(Other) <input type="checkbox"/>	
(Other) Convert to water injection		(Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)	

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

3410' PB.

Pull producing equipment. Clean out if necessary. Run 2-3/8" lined tubing and Guiberson tension type packer. Set packer at approximately 3225'. Load casing with treated water. Start injecting water.

RECEIVED
DEC-7 1972
U. S. GEOLOGICAL SURVEY
ARTESIA, NEW MEXICO

18. I hereby certify that the foregoing is true and correct

SIGNED H. J. Breysaale TITLE Area Engineer DATE December 5, 1972

(This space for Federal or State office use)

APPROVED BY
DEC 7 - 1972
H. L. BEEKMAN
ACTING DISTRICT ENGINEER

TITLE _____ DATE _____

*See Instructions on Reverse Side